



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

LONPAC INSURANCE BHD

DATE : 18-10-2022

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555

VEHICLE NO. : SMU2618R

ACCIDENT DATE : 17-10-2022 07:45

THIRD PARTY REF. : GV1289D

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SMU2618R MAZDA 6 4-DOOR SEDAN 2.0L SP.6EAT

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR LAMP RH <i>cut</i>	1593.00
2	1	REAR BUMPER <i>cut</i>	1266.00
3	1	REAR BUMPER SIDE RETAINER RH ?	59.00
4	10	REAR BUMPER CLIP @\$5.00 <i>m</i>	50.00
			2,968.00
LESS 20 %			
			593.60
TOTAL (A)			
			2,374.40

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	50.00 <i>30</i>
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	428.00 <i>300</i>
3	1	SPRAYPAINTING CHARGES	428.00 <i>400</i>
TOTAL (D)			890.00
ESTIMATE TOTAL			
			3,264.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ryan
Hp 90010068
3 days
4/5
10/10/22 @ 1015
Resy after repair