

Lee Wui Kuen
47 Namly Avenue
Singapore 267618

Not Notwork
L1 Rep & 240h
Repair After Paint
4 days

File No :
Date : 28-October-2022



Estimated cost of repair for vehicle no : SLZ8138E Toyota Altis
Accident involving vehicle no: SLZ8138E & YP1123S on 15.10.2022

Description	Quantity	Cost Price
Rear boot 852.90	1	\$ 852.90 ✓
Rear boot emblem	1	\$ 51.70 ✓
Rear boot badge "Corolla"	1	\$ 44.40 ✓
Rear boot badge "Altis"	1	\$ 49.40 ✓
Rear boot centre moulding with chrome	1	\$ 209.20 ✓
Rear boot inner lock	1	\$ 432.50 X
RH Rear boot inner tail lamp	1	\$ 509.80 X
LH Rear boot inner tail lamp 377.60	1	\$ 509.80 ✓
Rear boot weatherstrip	1	\$ 190.10 X
RH Rear boot hinge	1	\$ 75.60 X
LH Rear boot hinge	1	\$ 75.60 X
RH outer tail lamp	1	\$ 539.50 X
LH outer tail lamp 410.80	1	\$ 539.50 ✓
Rear bumper 602.60	1	\$ 602.60 ✓
Rear bumper clips (1 set)	1	\$ 35.00 ✓
Rear bumper reinforcement	1	\$ 432.50 X
RH Rear bumper inner bracket	1	\$ 118.70 X
LH Rear bumper inner bracket	1	\$ 118.70 X
Rear end panel	1	\$ 727.70 X
Rear end panel top trim	1	\$ 261.60 X
		258 \$ 6,376.80
		Less 20% \$ 1,275.36
		\$ 5,101.44

Rear number plate	1	S. nett	\$ 45.00 X
Rear parking sensors (1 set)	1	S. nett	\$ 260.00 X

To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member, to replace damaged parts and adjust rear body and rear boot alignment

\$ 700.00 400

To spray paint affected rear and inner damaged portion inclusive of preparatory works and material

\$ 650.00 600

File Pass to? ☐ : Prell. Report
☐ : Final Report
File Return to?

Days Of Repair: _____
Resurvey No. of Trip: _____
Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)

Survey Fee: _____
Transportation: _____
S-RS: \$ _____
Fees: _____

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality

\$ 50.00 201

To perform computer diagnostic on parking system, and clear fault codes

\$ 150.00 7

To apply anti-corrosion Tuff-Kote

\$ 100.00 301

\$ 7,056.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

to? ☐ : Prell. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee: _____

Transportation: _____

\$ - RS - \$

Add Fee: ☐ : Site Insp (\$ _____)