

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0887/2022/NK
DATE : 17-Oct-22
WIP : 46314

VEHICLE IN WORKSHOP. KINDLY ARRANGE SURVEY ON 18/10/2022 AT 24 BENOI SECTOR
YOUR INSURED VEH NO : SMD 9796 C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LEE WAN SEONG
ADDRESS : 2 PETIR ROAD
#23-11
SINGAPORE 678265
TELEPHONE : HP +65 96692311
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : SCP 2899 R
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 25/2/2021
ENGINE NO : DEM 028573
CHASSIS NO : WAUZZZF5XMA018779
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Oct-22
PLACE OF ACCIDENT : JUNCTION OD STEVENS ROAD AND DRAYCOTT DR

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCP 2899 R - FRONT

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 ²⁵⁰ ✓	
3 4	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00 ²⁸⁰ ₆₈₀ ✓	
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR, RHS REAR DOOR AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00 ^{4.5 x 500} ₂₂₅₀ ✓	
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR, RHS WING MIRROR AND RHS REAR DOOR.	\$ 5,500.00 ^{500 x 550 + 150} ₂₉₀₀ ✓	
TOTAL LABOUR CHARGES ^{by dis. handle R, L, etc} ₅₀		: \$ <u>11,980.00</u>	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCP 2899 R - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00 /	
2	TO RENEW RHS 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER	S/N \$ 300.00 /	
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS	S/N \$ 400.00 /	
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00 150 ✓	
5	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND REPAIR WHERE NECESSARY (photo)	S/N \$ 1,600.00 /	
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC. (photo)	S/N \$ 1,600.00 /	
SUB-TOTAL LABOUR CHARGES		: \$ 4,460.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCP 2899 R - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. TO CUT OUT AND WELD RHS REAR FENDER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>6 x 500</i>	\$ 6,400.00	3000 ✓
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL TRIM, ROOF CHANNEL, RHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING. <i>4.5 x 550</i>	\$ 6,500.00	2475 ✓
9	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY. S/N	\$ 2,400.00	7 X
10	TO REMOVE AND RENEW RHS REAR WHEEL SUSPENSION ASSY. S/N	\$ 2,400.00	7 X
11	TO RENEW RHS FRONT RIM WITH TYRE, RHS REAR RIM WITH TYRE AND LHS FRONT RIM. TO CARRY OUT PRE / POST WHEEL ALIGNMENT. <i>240 + 120</i>	\$ 600.00	360 ✓
12	TO CARRY OUT PRE / POST DIAGNOSTIC CHECK. S/N	\$ 384.00	✓
TOTAL LABOUR CHARGES		\$ 23,144.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCP 2899 R - FRONT

			DAMAGED PARTS & PRICES		REMARKS
S/N	PARTS DESCRIPTION	QTY	S/NETT		
1	FRONT BUMPER ✓ <i>DN</i>	1	\$	2,493.00 ✓	<i>1994.40</i>
2	FRONT BUMPER SECURING STRIPS ? X nn	2	\$	79.00	
3	FRONT BUMPER GRILLE - CENTER ? X nn	1	\$	219.00	
4	FRONT BUMPER CLOSING ELEMENT- LOWER CENTRE ? X 1 nn \$	1	\$	293.00	
5	FRONT BUMPER AIR GUIDE - RH ? X nn	1	\$	72.00	
6	FRONT BUMPER CLOSING ELEMENT ? X nn	1	\$	293.00	
7	FRONT BUMPER AIR GUIDE GRILLE RH ✓ <i>mis</i>	1	\$	151.00 ✓	<i>120.40</i>
8	FRONT BUMPER TRIM ? X nn	1	\$	54.00	
9	FRONT BUMPER BLACK TRIM - CENTRE ? X nn	1	\$	127.00	
10	RADIATOR GRILLE X nn	1	\$	1,881.00	
11	FRONT BUMPER SENSOR - OUTER ? X nn	1	\$	266.00	
12	FRONT SENSOR PARK ASSIST - SIDE ✓ <i>mi</i>	1	\$	266.00 ✓	<i>212.40</i>
13	FRONT SENSOR SEAL RING ✓ <i>me</i>	4	\$	10.00 ✓	<i>8</i>
14	WIRING SET FOR BUMPER ? X nn	1	\$	449.00	
15	HORN LOW TONE - RH ? X nn	1	\$	139.00	
16	SPRING SHACKLE - RH ? X nn	1	\$	33.00	
17	FRONT BUMPER FOAM FILLER PC X nn	1	\$	163.00	
18	FRONT REINFORCEMENT BEAM X nn	1	\$	899.00	
19	FRONT BUMPER GUIDE SECTION - RH ? X nn	1	\$	41.00	
20	FRONT BUMPER BRACKET - RH ? X nn	1	\$	254.00	
SUB TOTAL SPARE PARTS		:	\$	8,182.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OX) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCP 2899 R - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER TOP COVER X nn	1	\$ 143.00	
22	STICKER FOR "CAUTION" X nn	1	\$ 16.00	
23	STICKER FOR "AIR CONDITIONER" X nn	1	\$ 9.00	
24	FRONT BRACKET FOR LOCK CARRIER X nn	1	\$ 154.00	
25	FRONT BUMPER SUPPORT - LH / RH X nn	2	\$ 64.00	
26	POP RIVET X nn	4	\$ 4.00	
27	FRONT FENDER - RH / OK	1	\$ 1,189.00	✓ 951.20
28	FRONT FENDER ATTACHMENTS PARTS X nn	1	\$ 55.00	
29	FRONT FENDER CLOSING ELEMENT - RH / MC	1	\$ 83.00	✓ 65.84
30	FRONT FENDER BRACKET - RH / ST	1	\$ 41.00	✓ 32.72
31	POP RIVET - MC	6	\$ 23.00	✓ 18.24
32	FRONT FENDER BRACE - FRONT RH ? BT	1	\$ 132.00	✓ 105.20
33	FRONT FENDER BRACKET FOR DEFORMATION ELEMENT ?	1 X	\$ nn 55.00	
34	FRONT FENDER BRACKET LH / RH ? X nn	1	\$ 40.00	
35	FRONT WHEEL HOUSING LINERS RH / T1	1	\$ 299.00	✓ 238.80
36	FRONT WHEEL SPOILER RH - OR	1	\$ 82.00	✓ 65.12
37	FRONT SPOILER RH ? X nn	1	\$ 40.00	
38	STONE CHIP GUARD BLACK - RH / MC	1	\$ 57.00	✓ 45.28
39	FRONT FENDER FLEDGE COVER - LONG RH - OR	1	\$ 40.00	✓ 31.44
40	FRONT FENDER FLEDGE COVER - SHORT RH ? X nn	1	\$ 18.00	
SUB TOTAL SPARE PARTS			\$ 2,544.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCP 2899 R - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	HEADLIGHT TOP COVER - RH ✓ GR	1	\$ 49.00 ✓	38.64	
42	BONNET ✓ ON	1	\$ 3,491.00 ✓	2792.80	
43	BONNET IMPACT PROTECTION - CENTRE ✓ NC	1	\$ 31.00 ✓	24.72	
44	BONNET IMPACT PROTECTION - LH / RH ✓ NC	2	\$ 62.00 ✓	48.48	
45	BONNET STRICKER RH X nn	1	\$ 56.00		
46	BONNET LID LOCK X nn	1	\$ 228.00		
47	BONNET BOWDEN CABLE - CENTRE X nn	1	\$ 64.00		
48	BONNET RELEASE LEVER - CENTRE X nn	1	\$ 15.00		
49	BONNET BOWDEN CABLE - CENTRE X nn	1	\$ 64.00		
50	BONNET BOWDEN CABLE COVER X nn	1	\$ 11.00		
51	FRONT FENDER CHROME TRIM RH ✓ NC	1	\$ 171.00 ✓	136.40	
52	FRONT FENDER CLOSING ELEMENT - RH ? X nn	1	\$ 37.00		
53	FRONT FENDER CLOSING ELEMENT COVER - RH ? X nn	1	\$ 20.00		
54	LED HEADLIGHT WITH MATRIX BEAM - RH ✓ GR	1	\$ 8,172.00 ✓	6537.60	
55	HEADLIGHT HOSE ? X nn	1	\$ 42.00		
56	HEADLIGHT COMPENSATING HOSE 10MM 1 X nn	1	\$ 45.00		
57	HEADLIGHT COMPENSATING HOSE - 0.8MM 2 X nn	1	\$ 47.00		
58	HEADLIGHT COMPENSATING PC 2 X nn	1	\$ 45.00		
59	HEADLIGHT BRACKET FOR LIFT CYLINDER - RH ? X nn	1	\$ 17.00		
60	HEADLIGHT LIFT CYLINDER - RH 2 X nn	1	\$ 217.00		
SUB TOTAL SPARE PARTS			: \$ 12,884.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SCP 2899 R - FRONT

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
61	LIFT CYLINDER HOSE - LONG ¹ X nn	1	\$	107.00	
62	LIFT CYLINDER HOSE - SHORT ¹ X nn	1	\$	53.00	
63	HEADLIGHT WATER RESERVOIR TANK ¹ X nn	1	\$	154.00	
64	FRONT DOOR - RH X R	1	\$	3,977.00	
65	FRONT DOOR OUTER DOOR SEAL - RH X nn	1	\$	247.00	
66	FRONT DOOR BONDING AGENT X nn	1	\$	51.00	
67	CLEANING SOLUTION 250 ML X nn	1	\$	74.00	
68	CLEANING SOLUTION APPLICATOR V nn	1	\$	9.00	
69	FRONT DOOR CATCH - RH X nn	1	\$	134.00	
70	FRONT DOOR TRIM - RH 1 - ne	1	\$	171.00 ✓	136.40
71	EXTERIOR MIRROR MOUNTING - RH - cut	1	\$	2,015.00 ✓	1612
72	EXTERIOR MIRROR CAP RH - cut	1	\$	308.00 ✓	246
73	EXTERIOR MIRROR GLASS - RH X nn	1	\$	1,757.00	
74	FRONT WINDOW SLOT SEAL - RH X nn	1	\$	446.00	
75	DATA PLATE FOR TYRE PRESSURE X nn	1	\$	41.00	
76	REAR DOOR RH / on	1	\$	3,977.00 ✓	3181.60
77	REAR DOOR OUTER DOOR SEAL - RH / ne	1	\$	247.00 ✓	197.20
78	REAR DOOR SEAL BONDING AGENT 30 ML - ne	1	\$	51.00 ✓	40.56
79	CLEANING SOLUTION 250 ML - ne	1	\$	74.00 ✓	58.96
80	APPLICATOR ne X nn	1	\$	9.00	
SUB TOTAL SPARE PARTS		:	\$	13,902.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO, SCP 2899 R - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
81	REAR DOOR ATTACHMENTS PARTS - REAR <i>Wipe ?</i>	1	\$ nec	180.00 ✓	1444
82	REAR DOOR CATCH <i>? X nn</i>	1	\$	134.00	
83	REAR DOOR HANDLE TRIM - RH <i>/ MIS</i>	1	\$	98.00 ✓	77.92
84	REAR DOOR HANDLE TRIM COVER - RH <i>/ MIS</i>	1	\$	7.00 ✓	5.36
85	REAR DOOR HANDLE TRIM HOUSING <i>? X nn</i>	1	\$	9.00	
86	REAR DOOR PEDIPHERAL LIGHT REAR - RH <i>? X nn</i>	1	\$	81.00	
87	REAR DOOR HANDLE SENSOR - RH <i>? X nn</i>	1	\$	255.00	
88	REAR DOOR HANDLE EXTERIOR - RH <i>/ BR</i>	1	\$	47.00 ✓	37.12
89	UNDERLAY FRONT / REAR - RH <i>/ MC</i>	2	\$	8.00 ✓	6.40
90	REAR DOOR MOUNTING BAR - RH <i>? X nn</i>	1	\$	183.00	
91	SECTIONAL PART - RH (For L RH) <i>/ CH</i>	1	\$	4,076.00 ✓	3260.80
92	RIVETTED CAP NUT <i>/ MC X nn</i>	2	\$	7.00	
93	1/4 GALSS <i>/ MC</i>	1	\$	780.00 ✓	638
94	1/4 GLASS PRIMER <i>/ MC</i>	1	\$	22.00 ✓	17.36
95	1/4 GALSS INSERT <i>/ MC X nn</i>	1	\$	100.00	
96	REAR WHEEL HOUSING LINERS RH <i>? TN</i>	1	\$	299.00 ✓	238.80
TOTAL SPARE PARTS			:	\$ 43,798.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCP 2899 R - REAR

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>GR</i>	1 S	2,609.00	✓ 2087.20
2	REAR BUMPER GUIDE SECTION LOWER/ UPPER - RH <i>1 X</i>	2 nn S	75.00	
3	REAR BUMPER SENSOR FOR PARK ASSIST REAR - SIDE <i>1 X</i>	1 nn S	266.00	
4	REAR BUMPER SENSOR SEAL <i>1 X</i>	4 S	10.00	
5	LED TAILLIGHT - RH <i>1 X</i>	1 S	1,269.00	
6	LED TAILLIGHT ATTACHMENTS PARTS <i>1 X</i>	1 S	136.00	
7	LED TAILLIGHT ADHESIVE TAPES <i>1 X</i>	1 S	221.00	
8	ALUMINIUM RIM <i>(Front R, L & Rear RH) 1/14</i> <i>3</i>	3 S	7,677.00	✓ 6144.60
9	ALUMINIUM RIM RUBBER VALVE <i>1 X</i>	3 S	12.00	✓ 8.98
10	FRONT WISHBONE LINK RH <i>1 X</i>	1 S	605.00	
11	LOWER ARM FRONT - RH <i>1 X</i>	1 S	1,057.00	
12	FRONT UPPER ARM FRONT / REAR - RH <i>1 X</i>	2 S	1,150.00	
13	FRONT WHEEL HOUSING BEARING - RH <i>1 X</i>	1 S	1,070.00	
14	FRONT LOWER ARM SWIVEL JOINT <i>1 X</i>	1 S	214.00	
15	FRONT WHEEL HUB - RH <i>1 X</i>	1 S	499.00	
16	FRONT WHEEL HUB BEARING - RH <i>1 X</i>	1 S	273.00	
17	FRONT SUSPENSION FORKS- RH <i>1 X</i>	1 S	293.00	
18	FRONT COUPLING ROD <i>1 X</i>	2 S	258.00	
19	FRONT GAS SHOCK ABSORBER - RH <i>1 X</i>	1 S	342.00	
20	FRONT TIE ROD - RH <i>1 X</i>	1 S	109.00	
SUB TOTAL SPARE PARTS		:	\$ 18,145.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SCP 2899 R - REAR

		DAMAGED PARTS & PRICES			REMARKS
S/N	PARTS DESCRIPTION	QTY	S/NETT		
21	FRONT TIE ROD END RH 1 X nn	1	\$	217.00	
22	REAR LOWER ARM - RH 1 X nn	1	\$	963.00	
23	REAR WISHBONE UPPER - RH 1 X nn	1	\$	624.00	
24	REAR WISHBONE UPPER - RH FRONT 1 X nn	1	\$	137.00	
25	REAR WISHBONE - RH REAR 1 X nn	1	\$	501.00	
26	REAR TRACK ROD REAR - RH REAR 1 X nn	1	\$	188.00	
27	REAR WHEEL BEARING HOUSING RH 1 X nn	1	\$	1,097.00	
28	REAR WHEEL HUB BEARING - RH 1 X nn	1	\$	723.00	
29	REAR GAS SHOCK ABSORBER - RH 1 X nn	1	\$	342.00	
30	REAR COUPLING ROD - RH 1 X nn	1	\$	94.00	
31	FRONT NO PLATE X nn	SN	\$	60.00	
32	ACYRLIC SEALER - K	SN	\$	180.00	✓ 180
33	CAVITY WAX - K	SN	\$	140.00	✓ 140
34	STONE CHIP - K	SN	\$	180.00	✓ 180
35	METAL FILLER POWDER - K	SN	\$	280.00	✓ 280
36	1/4 GLASS SEALANT - K	SN	\$	100.00	✓ 100
37	RHS FRONT TYRE - T1	SN	TBC	430	✓ 430
38	RHS REAR TYRE X nn	SN	TBC		
39	SUNDRIES 1 nec	1	\$	1,000.00	173.44 ✓
TOTAL SPARE PARTS		:	\$	24,971.00	
TOTAL SPARE PARTS FRONT AND REAR			\$	68,769.00	
TOTAL LABOUR CHARGES			\$	35,124.00	
GRAND TOTAL			\$	103,893.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

★ PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : STEW (LKK)
SURVEYED DATE : 18/10/22, 3.30pm
AUTHORISED DATE : 02/11/22
EXCESS COST : EXCESS - ?
LIABILITY : PIP
REMARKS : MY BL 4, 21 dys

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

(car pm 14, L1 pm 7)
Inch Ahy4

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: