

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0887/2022/NK
DATE : 17-Oct-22
WIP : 46314

VEHICLE IN WORKSHOP. KINDLY ARRANGE SURVEY ON 18/10/2022 AT 24 BENOI SECTOR
YOUR INSURED VEH NO : SMD 9796 C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

21 days - ok - Johnny Boo

11-Jan-23

OWNER'S NAME : MR LEE WAN SEONG
ADDRESS : 2 PETIR ROAD
#23-11
SINGAPORE 678265
TELEPHONE : HP +65 96692311
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SCP 2899 R**
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 25/2/2021
ENGINE NO : DEM 028573
CHASSIS NO : WAUZZZF5XMA018779
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Oct-22
PLACE OF ACCIDENT : JUNCTION OD STEVENS ROAD AND DRAYCOTT DR

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCP 2899 R - FRONT

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	800.00	\$	680.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR, RHS REAR DOOR AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,800.00	\$	2,250.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR, RHS WING MIRROR AND RHS REAR DOOR.	\$	5,500.00	\$	2,900.00
TOTAL LABOUR CHARGES		:	\$ 11,980.00	\$	6,560.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCP 2899 R - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 6,560.00
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
2	TO RENEW RHS 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER	S/N \$	300.00	\$ 300.00
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS	S/N \$	400.00	\$ 400.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	\$ 150.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AMD RENEW WHERE NECESSARY	S/N \$	1,600.00	\$ 1,600.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST , HAT TRAY, CD PILLAR TRIMS. LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	\$ 1,600.00
SUB-TOTAL LABOUR CHARGES		:	\$ 4,460.00	\$ 10,970.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCP 2899 R - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$	10,970.00
7	TO DISMANTLE AND RENEW REAR BUMPER. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. TO CUT OUT AND WELD RHS REAR FENDER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,400.00	\$	3,000.00
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL TRIM, ROOF CHANNEL, RHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.	\$	6,500.00	\$	2,475.00
9	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY.	S/N \$	2,400.00		
10	TO REMOVE AND RENEW RHS REAR WHEEL SUSPENSION ASSY.	S/N \$	2,400.00		
11	TO RENEW RHS FRONT RIM WITH TYRE, RHS REAR RIM WITH TYRE AND LHS FRONT RIM. TO CARRY OUT PRE / POST WHEEL ALIGNMENT.	S/N \$	600.00	\$	360.00
12	TO CARRY OUT PRE / POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$	384.00
TOTAL LABOUR CHARGES		:	\$	23,144.00	\$ 17,189.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SCP 2899 R - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,493.00	\$	1,994.40
2	FRONT BUMPER SECURING STRIPS	2	\$ 79.00		
3	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00		
4	FRONT BUMPER CLOSING ELEMENT- LOWER CENTRE	1	\$ 293.00		
5	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00		
6	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00		
7	FRONT BUMPER AIR GUIDE GRILLE RH	1	\$ 151.00	\$	120.40
8	FRONT BUMPER TRIM	1	\$ 54.00		
9	FRONT BUMPER BLACK TRIM - CENTRE	1	\$ 127.00		
10	RADIATOR GRILLE	1	\$ 1,881.00		
11	FRONT BUMPER SENSOR - OUTER	1	\$ 266.00		
12	FRONT SENSOR PARK ASSIST - SIDE	1	\$ 266.00	\$	212.40
13	FRONT SENSOR SEAL RING	4	\$ 10.00	\$	8.00
14	WIRING SET FOR BUMPER	1	\$ 449.00		
15	HORN LOW TONE - RH	1	\$ 139.00		
16	SPRING SHACKLE - RH	1	\$ 33.00		
17	FRONT BUMPER FOAM FILLER PC	1	\$ 163.00		
18	FRONT REINFORCEMENT BEAM	1	\$ 899.00		
19	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00		
20	FRONT BUMPER BRACKET - RH	1	\$ 254.00		
SUB TOTAL SPARE PARTS		:	\$ 8,182.00	\$	2,335.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SCP 2899 R - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 2,335.20
21	FRONT BUMPER TOP COVER	1	\$ 143.00	
22	STICKER FOR "CAUTION"	1	\$ 16.00	
23	STICKER FOR " AIR CONDITIONER"	1	\$ 9.00	
24	FRONT BRACKET FOR LOCK CARRIER	1	\$ 154.00	
25	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	
26	POP RIVET	4	\$ 4.00	
27	FRONT FENDER - RH	1	\$ 1,189.00	\$ 951.20
28	FRONT FENDER ATTACHMENTS PARTS	1	\$ 55.00	
29	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 83.00	\$ 65.84
30	FRONT FENDER BRACKET - RH	1	\$ 41.00	\$ 32.72
31	POP RIVET	6	\$ 23.00	\$ 18.24
32	FRONT FENDER BRACE - FRONT RH	1	\$ 132.00	\$ 105.20
33	FRONT FENDER BRACKET FOR DEFORMATION ELEMENT	1	\$ 55.00	
34	FRONT FENDER BRACKET LH / RH	1	\$ 40.00	
35	FRONT WHEEL HOUSING LINERS RH	1	\$ 299.00	\$ 238.80
36	FRONT WHEEL SPOILER RH	1	\$ 82.00	\$ 65.12
37	FRONT SPOILR RH	1	\$ 40.00	
38	STONE CHIP GUARD BLACK - RH	1	\$ 57.00	\$ 45.28
39	FRONT FENDER FLEDGE COVER - LONG RH	1	\$ 40.00	\$ 31.44
40	FRONT FENDER FLEDGE COVER - SHORT RH	1	\$ 18.00	
SUB TOTAL SPARE PARTS			\$ 2,544.00	\$ 3,889.04

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SCP 2899 R - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	3,889.04
41	HEADLIGHT TOP COVER- RH	1	\$ 49.00	\$	38.64
42	BONNET	1	\$ 3,491.00	\$	2,792.80
43	BONNET IMPACT PROTECTION- CENTRE	1	\$ 31.00	\$	24.72
44	BONNET IMPACT PROTECTION- LH / RH	2	\$ 62.00	\$	48.48
45	BONNET STRICKER RH	1	\$ 56.00		
46	BONNET LID LOCK	1	\$ 228.00		
47	BONNET BOWDEN CABLE - CENTRE	1	\$ 64.00		
48	BONNET RELEASE LEVER- CENTRE	1	\$ 15.00		
49	BONNET BOWDEN CABLE - CENTRE	1	\$ 64.00		
50	BONNET BOWDEN CABLE COVER	1	\$ 11.00		
51	FRONT FENDER CHROME TRIM RH	1	\$ 171.00	\$	136.40
52	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 37.00		
53	FRONT FENDER CLOSING ELEMENT COVER - RH	1	\$ 20.00		
54	LED HEADLIGHT WITH MATRIX BEAM - RH	1	\$ 8,172.00	\$	6,537.60
55	HEADLIGHT HOSE	1	\$ 42.00		
56	HEADLIGHT COMPENSATING HOSE 10MM	1	\$ 45.00		
57	HEADLIGHT COMPENSATING HOSE - 0.8MM	1	\$ 47.00		
58	HEADLIGHT COMPENSATING PC	1	\$ 45.00		
59	HEADLIGHT BRACKET FOR LIFT CYCLINDER - RH	1	\$ 17.00		
60	HEADLIGHT LIFT CYLINDER - RH	1	\$ 217.00		
SUB TOTAL SPARE PARTS		:	\$ 12,884.00	\$	13,467.68

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SCP 2899 R - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 13,467.68
61	LIFT CYCLINDER HOSE - LONG	1	\$ 107.00	
62	LIFT CYCLINDER HOSE - SHORT	1	\$ 53.00	
63	HEADLIGHT WATER RESERVOIR TANK	1	\$ 154.00	
64	FRONT DOOR - RH	1	\$ 3,977.00	
65	FRONT DOOR OUTER DOOR SEAL - RH	1	\$ 247.00	
66	FRONT DOOR BONDING AGENT	1	\$ 51.00	
67	CLEANING SOLUTION 250 ML	1	\$ 74.00	
68	CLEANING SOLUTION APPLICATOR	1	\$ 9.00	
69	FRONT DOOR CATCH - RH	1	\$ 134.00	
70	FRONT DOOR TRIM - RH	1	\$ 171.00	\$ 136.40
71	EXTERIOR MIRROR MOUNTING- RH	1	\$ 2,015.00	\$ 1,612.00
72	EXTERIOR MIRROR CAP RH	1	\$ 308.00	\$ 246.00
73	EXTERIOR MIRROR GLASS- RH	1	\$ 1,757.00	
74	FRONT WINDOW SLOT SEAL - RH	1	\$ 446.00	
75	DATA PLATE FOR TYRE PRESSURE	1	\$ 41.00	
76	REAR DOOR RH	1	\$ 3,977.00	\$ 3,181.60
77	REAR DOOR OUTER DOOR SEAL - RH	1	\$ 247.00	\$ 197.20
78	REAR DOOR SEAL BONDING AGENT 30 ML	1	\$ 51.00	\$ 40.56
79	CLEANING SOLUTION 250 ML	1	\$ 74.00	\$ 58.96
80	APPLICATOR	1	\$ 9.00	
SUB TOTAL SPARE PARTS			\$ 13,902.00	\$ 18,940.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SCP 2899 R - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	18,940.40
81	REAR DOOR ATTACHMENTS PARTS - REAR	1	\$ 180.00	\$	144.00
82	REAR DOOR CATCH	1	\$ 134.00		
83	REAR DOOR HANDLE TRIM - RH	1	\$ 98.00	\$	77.92
84	REAR DOOR HANDLE TRIM COVER - RH	1	\$ 7.00	\$	5.36
85	REAR DOOR HANDLE TRIM HOUSING	1	\$ 9.00		
86	REAR DOOR PEDIPHERAL LIGHT REAR -RH	1	\$ 81.00		
87	REAR DOOR HANDLE SENSOR - RH	1	\$ 255.00		
88	REAR DOOR HANDLE EXTERIOR - RH	1	\$ 47.00	\$	37.12
89	UNDERLAY FRONT / REAR - RH	2	\$ 8.00	\$	6.40
90	REAR DOOR MOUNTING BAR - RH	1	\$ 183.00		
91	SECTIONAL PART - RH	1	\$ 4,076.00	\$	3,260.80
92	RIVETTED CAP NUT	2	\$ 7.00		
93	1/4 GALSS	1	\$ 780.00	\$	638.00
94	1/4 GLASS PRIMER	1	\$ 22.00	\$	17.36
95	1/4 GALSS INSERT	1	\$ 100.00		
96	REAR WHEEL HOUSING LINERS RH	1	\$ 299.00	\$	238.80
TOTAL SPARE PARTS			\$ 43,798.00	\$	23,366.16

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SCP 2899 R - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 23,366.16
1	REAR BUMPER	1	\$ 2,609.00	\$ 2,087.20
2	REAR BUMPER GUIDE SECTION LOWER/ UPPER - RH	2	\$ 75.00	
3	REAR BUMPER SENSOR FOR PARK ASSIST REAR - SIDE	1	\$ 266.00	
4	REAR BUMPER SENSOR SEAL	4	\$ 10.00	
5	LED TAILLIGHT - RH	1	\$ 1,269.00	
6	LED TAILLIGHT ATTACHMENTS PARTS	1	\$ 136.00	
7	LED TAILLIGHT ADHESIVE TAPES	1	\$ 221.00	
8	ALUMINIUM RIM	3	\$ 7,677.00	\$ 6,141.60
9	ALUMINIUM RIM RUBBER VALVE	3	\$ 12.00	\$ 8.88
10	FRONT WISHBONE LINK RH	1	\$ 605.00	
11	LOWER ARM FRONT - RH	1	\$ 1,057.00	
12	FRONT UPPER ARM FRONT / REAR - RH	2	\$ 1,150.00	
13	FRONT WHEEL HOUSING BEARING - RH	1	\$ 1,070.00	
14	FRONT LOWER ARM SWIVEL JOINT	1	\$ 214.00	
15	FRONT WHEEL HUB - RH	1	\$ 499.00	
16	FRONT WHEEL HUB BEARING - RH	1	\$ 273.00	
17	FRONT SUSPENSION FORKS- RH	1	\$ 293.00	
18	FRONT COUPLING ROD	2	\$ 258.00	
19	FRONT GAS SHOCK ABSORBER - RH	1	\$ 342.00	
20	FRONT TIE ROD - RH	1	\$ 109.00	
SUB TOTAL SPARE PARTS		:	\$ 18,145.00	\$ 31,603.84

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SCP 2899 R - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 31,603.84
21	FRONT TIE ROD END RH	1	\$ 217.00	
22	REAR LOWER ARM - RH	1	\$ 963.00	
23	REAR WISHBONE UPPER - RH	1	\$ 624.00	
24	REAR WISHBONE UPPER - RH FRONT	1	\$ 137.00	
25	REAR WISHBONE - RH REAR	1	\$ 501.00	
26	REAR TRACK ROD REAR - RH REAR	1	\$ 188.00	
27	REAR WHEEL BEARING HOUSING RH	1	\$ 1,097.00	
28	REAR WHEEL HUB BEARING - RH	1	\$ 723.00	
29	REAR GAS SHOCK ABSORBER - RH	1	\$ 342.00	
30	REAR COUPLING ROD - RH	1	\$ 94.00	
31	FRONT NO PLATE	SN	\$ 60.00	
32	ACYRLIC SEALER	SN	\$ 180.00	\$ 180.00
33	CAVITY WAX	SN	\$ 140.00	\$ 140.00
34	STONE CHIP	SN	\$ 180.00	\$ 180.00
35	METAL FILLER POWDER	SN	\$ 280.00	\$ 280.00
36	1/4 GLASS SEALANT	SN	\$ 100.00	\$ 100.00
37	RHS FRONT TYRE	SN	\$ 430.00	\$ 430.00
38	RHS REAR TYRE	SN	TBC	
39	SUNDRIES	1	\$ 1,000.00	\$ 173.44
TOTAL SPARE PARTS			\$ 25,401.00	\$ 33,087.28
TOTAL SPARE PARTS FRONT AND REAR			\$ 69,199.00	\$ 33,087.28
TOTAL LABOUR CHARGES			\$ 35,124.00	\$ 17,189.00
GRAND TOTAL			\$ 104,323.00	\$ 50,276.28

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-07/12/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT