


# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0900/2022/NK  
DATE : 17-Oct-22  
WIP : 46323

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/10/2022  
AT 24 BENOI SECTOR.

## AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR EDMOND LIM CHYE KWANG  
ADDRESS : BLK 9 SELEGIE ROAD  
# 08-19  
SINGAPORE 180009  
  
TELEPHONE : HP +65 98567415  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2070125628-02  
VEHICLE NO : SMU 7703 U  
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC  
MODEL YEAR : 27/8/2020  
ENGINE NO : DEM 025004  
CHASSIS NO : WAUZZZF41LN016210  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 14-Oct-22  
PLACE OF ACCIDENT : INFRONT OF EIGHT RIVER SUITES

Car in

wip: 46323

Benz



# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIG-star

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 7703 U

|                       |                                               |     |             | DAMAGED PARTS & PRICES |           |
|-----------------------|-----------------------------------------------|-----|-------------|------------------------|-----------|
| S/N                   | PARTS DESCRIPTION                             | QTY | S/NETT      | REMARKS                |           |
| 1                     | FRONT BUMPER ✓ BR                             | 1   | \$ 2,377.00 |                        | 1901.60   |
| 2                     | FRONT BUMPER FIXING PARTS X ?                 | 1   | \$ 393.00   | X                      | } nn      |
| 3                     | FRONT BUMPER SECURING STRIP                   | 2   | \$ 79.00    | X                      |           |
| 4                     | FRONT BUMPER GRILLE - CENTRE X                | 1   | \$ 219.00   | X                      |           |
| 5                     | FRONT BUMPER CLOSING ELEMENT CENTRE- LOWER ?  | 1   | \$ 293.00   |                        | 234.00 de |
| 6                     | FRONT BUMPER AIR GUIDE GRILLE - LH / BR       | 1   | \$ 51.00    | X n                    |           |
| 7                     | FRONT BUMPER CLOSING ELEMENT CENTRE - UPPER ? | 1   | \$ 293.00   | X n                    |           |
| 8                     | FRONT BUMPER AIR GUIDE GRILLE BLACK- LH ?     | 1   | \$ 151.00   |                        | 120.40    |
| 9                     | FRONT BUMPER TRIM - LH X ?                    | 1   | \$ 54.00    | X n                    |           |
| 10                    | RADIATOR GRILLE / BR                          | 1   | \$ 1,754.00 |                        | 1403.20   |
| 11                    | FRONT BUMPER FOAM FILLER ? - BR               | 1   | \$ 212.00   |                        | 169.20    |
| 12                    | FRONT BUMPER CARRIER ? - BR                   | 1   | \$ 899.00   |                        | 719.20    |
| 13                    | FRONT BUMPER BRACKET - LH ✓                   | 1   | \$ 254.00   | X n                    |           |
| 14                    | FRONT BUMPER GUIDE SECTION - LH / BR          | 1   | \$ 41.00    |                        | 32.24     |
| 15                    | FRONT BUMPER TOP COVER / BR                   | 1   | \$ 143.00   |                        | 114.00    |
| 16                    | "CAUTION" SIGN STICKER - n                    | 1   | \$ 16.00    |                        | 12.40     |
| 17                    | AIR CONDITIONER STICKER - n                   | 1   | \$ 9.00     |                        | 6.64      |
| 18                    | FRONT BUMPER BRACKET / BR                     | 1   | \$ 154.00   |                        | 122.80    |
| 19                    | FRONT BUMPER SUPPORT LH RH ? - n              | 2   | \$ 64.00    |                        | 51.04     |
| 20                    | SIGNAL HORN HIGH TONE- LH ?                   | 1   | \$ 134.00   | X n                    |           |
| SUB TOTAL SPARE PARTS |                                               |     | \$ 7,590.00 |                        |           |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 7703 U**

|                              |                                                 |     | DAMAGED PARTS & PRICES |         |
|------------------------------|-------------------------------------------------|-----|------------------------|---------|
| S/N                          | PARTS DESCRIPTION                               | QTY | S/NETT                 | REMARKS |
| 21                           | SPRING SHACKLE LH ?                             | 1   | \$ 33.00               | X       |
| 22                           | FRONT BUMPER SENSOR FRONT - INNER X             | 1   | \$ 266.00              | X       |
| 23                           | FRONT BUMPER SENSOR FRONT - OUTER ?             | 1   | \$ 266.00              | X       |
| 24                           | FRONT SENSOR SEAL RING - MC                     | 4   | \$ 10.00               |         |
| 25                           | FRONT FENDER - LH DD                            | 1   | \$ 1,227.00            |         |
| 26                           | FRONT FENDER ATTACHMENTS PARTS ?                | 1   | \$ 225.00              | X un    |
| 27                           | FRONT FENDER CLOSING ELEMENTS LH BT             | 1   | \$ 81.00               |         |
| 28                           | FRONT FENDER BRACKET - LH BT                    | 1   | \$ 41.00               |         |
| 29                           | FRONT FENDER BRACE FRONT - LH ?                 | 1   | \$ 132.00              | X       |
| 30                           | FRONT FENDER BRACKET DEFORMATION ELEMENT - LH X | 1   | \$ 55.00               | X       |
| 31                           | FRONT FENDER BRACKET - LOWER LH / RH X          | 1   | \$ 36.00               | X       |
| 32                           | FRONT WHEEL HOUSING LINER - LH ?                | 1   | \$ 256.00              | X       |
| 33                           | FRONT WHEEL SPOILER UPPER - LH ?                | 1   | \$ 82.00               | X       |
| 34                           | FRONT WHEEL SPOILER LOWER - LH ?                | 1   | \$ 39.00               | X       |
| 35                           | FRONT BUMPER TOP COVER - LH BR                  | 1   | \$ 35.00               |         |
| 36                           | FRONT HEADLAMP COVER - LH                       | 1   | \$ 49.00               |         |
| 37                           | BONNET DD                                       | 1   | \$ 3,425.00            |         |
| 38                           | BONNET ATTACHMENTS PARTS X                      | 1   | \$ 431.00              | X       |
| 39                           | BONNET LID HINGE LH / RH ?                      | 2   | \$ 680.00              | X       |
| 40                           | BONNET IMPACT PROTECTION - CENTRE - MC          | 1   | \$ 31.00               |         |
| <b>SUB TOTAL SPARE PARTS</b> |                                                 |     | <b>\$ 7,400.00</b>     |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) - APPROVED, REMARKS (X) - NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 7703 U**

| S/N                          | PARTS DESCRIPTION                            | QTY | DAMAGED PARTS & PRICES |   | REMARKS     |
|------------------------------|----------------------------------------------|-----|------------------------|---|-------------|
|                              |                                              |     | S/NETT                 |   |             |
| 41                           | BONNET IMPACT PROTECTION - LH / RH ✓ MC      | 2   | \$ 62.00               |   | 48.48       |
| 42                           | BONNET STRICKER - LH ✓ GT                    | 1   | \$ 56.00               |   | 44.36       |
| 43                           | BONNET LID LOCK ✓ BT                         | 1   | \$ 228.00              |   | 182.00      |
| 44                           | FRONT BOWDEN CABLE CENTRE ?                  | 1   | \$ 64.00               | X | } un        |
| 45                           | FRONT BOWDEN CABLE COVER ?                   | 1   | \$ 11.00               | X |             |
| 46                           | FRONT BOWDEN CABLE ?                         | 1   | \$ 64.00               | X |             |
| 47                           | FRONT BONNET RELEASE LEVER ?                 | 1   | \$ 15.00               | X |             |
| 48                           | FRONT LED HEADLIGHT LH ✓ BR                  | 1   | \$ 8,172.00            |   | 6537.60     |
| 49                           | FRONT LED HEADLIGHT HOSE ?                   | 1   | \$ 42.00               | X | } un        |
| 50                           | FRONT LED HEADLIGHT COMPENSATING PC 10MM ?   | 1   | \$ 45.00               | X |             |
| 51                           | FRONT LED HEADLIGHT COMPENSATING PC 0.8 MM ? | 2   | \$ 92.00               | X |             |
| 52                           | FRONT LIFT CYLINDER LH ?                     | 1   | \$ 231.00              | X |             |
| 53                           | FRONT LIFT CYLINDER BRACKET ?                | 1   | \$ 7.00                | ✓ | 5.44 dis    |
| 54                           | FRONT LIFT CYLINDER CORRUGATED PIPE ?        | 1   | \$ 107.00              | X | un          |
| 55                           | WIRING SET FOR BUMPER ?                      | 1   | \$ 642.00              | X | un          |
| 56                           | FRONT LOCK CARRIER ✓ BR                      | 1   | \$ 1,478.00            |   | 901.60      |
| 57                           | FRONT LOCK CARRIER BRACKET ?                 | 1   | \$ 21.00               | ✓ | 16.32 crn ✓ |
| 58                           | CHARGE AIR COOLER X                          | 1   | \$ 654.00              | X | } un        |
| 59                           | PRESSURE PIPE - LH ?                         | 1   | \$ 496.00              | X |             |
| 60                           | AIR CONDENSER ?                              | 1   | \$ 683.00              | X |             |
| <b>SUB TOTAL SPARE PARTS</b> |                                              |     | <b>\$ 13,170.00</b>    |   |             |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 7703 U

| S/N                  | PARTS DESCRIPTION           | QTY | DAMAGED PARTS & PRICES |           | REMARKS    |
|----------------------|-----------------------------|-----|------------------------|-----------|------------|
|                      |                             |     | S/NETT                 |           |            |
| 61                   | REFRIGERANT LINE SHORT      | 1   | \$                     | 186.00    | X          |
| 62                   | REFRIGERANT LINE LONG       | 1   | \$                     | 381.00    | X          |
| 63                   | REFRIGERANT LINE LOWER      | 1   | \$                     | 277.00    | X          |
| 64                   | REFRIGERANT PIPE            | 1   | \$                     | 585.00    | X          |
| 65                   | REFRIGERANT PIPE BRACKET    | 1   | \$                     | 9.00      | X          |
| 66                   | COOLANT IL                  | 6   | \$                     | 297.00    | 237.12     |
| 67                   | FRONT AIR GUIDE OUTER - LH  | 1   | \$                     | 51.00     | X          |
| 68                   | FRONT AIR GUIDE INNER - LH  | 1   | \$                     | 19.00     | 14.64      |
| 69                   | FRONT AIR GUIDE UPPER       | 1   | \$                     | 19.00     | X          |
| 70                   | FRONT WINDOW SLOT SEAL - LH | 1   | \$                     | 344.00    | X          |
| 71                   | FRONT NO PLATE              | S/N | \$                     | 60.00     | 60.00      |
| 72                   | SUNDRIES                    | 1   | \$                     | 400.00    | 86.56 net. |
| TOTAL SPARE PARTS    |                             | :   | \$                     | 30,788.00 |            |
| TOTAL LABOUR CHARGES |                             | :   | \$                     | 11,582.00 |            |
| GRAND TOTAL          |                             | :   | \$                     | 42,370.00 |            |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323, FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 7703 U

| S/N                  | NATURE OF JOBS                                                                                                                                                          | ESTIMATED CHARGES      | SURVEYOR'S RECOMMENDATIONS |
|----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|----------------------------|
| 1                    | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING ATD.                        | S/N \$ 480.00 ✓        |                            |
| 2                    | TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                                   | S/N \$ 350.00 250      |                            |
| 3                    | TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR, CHECK ELECTRICAL FANS AND CONTROL UNIT, PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. | S/N \$ 1,400.00 ? / ac |                            |
| 4                    | TO RENEW LHS FRONT FENDER INNER AIRCON PIPE.                                                                                                                            | S/N \$ 280.00 ? X nm.  |                            |
| 5                    | TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.                                | S/N \$ 280.00 ✓        |                            |
| TOTAL LABOUR CHARGES |                                                                                                                                                                         | : \$ <u>2,790.00</u>   |                            |

 **PREMIUM AUTOMOBILES**




55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 7703 U**

| S/N                         | NATURE OF JOBS                                                                                                                                                                                          | ESTIMATED CHARGES        | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|----------------------------|
| 6                           | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | \$ 4,900.00<br>5.5 x 577 | 2750 3000                  |
| 7                           | TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR                                                                                                                                    | \$ 3,700.00<br>4 x 550   | 2200                       |
| 8                           | TO CARRY OUT PRE / POST DIAGNOSTIC CHECK.                                                                                                                                                               | S/N \$ 192.00            | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                         | <b>\$ 11,582.00</b>      |                            |

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME  
SURVEYED DATE  
AUTHORISED DATE  
EXCESS COST  
LIABILITY  
REMARKS

Star (LKK)

18/10/77. 2.31pm

OD. M AL

EXCESS ?

PIP

by DIL 4, 10 days

14 days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: