

Car in

wipi 46323

Bensi



Aig-stap

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 7703 U

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER ✓ BR	1	\$	2,377.00
2	FRONT BUMPER FIXING PARTS X ?	1	\$	393.00
3	FRONT BUMPER SECURING STRIP	2	\$	79.00
4	FRONT BUMPER GRILLE - CENTRE X ?	1	\$	219.00
5	FRONT BUMPER CLOSING ELEMENT CENTRE- LOWER	1	\$	293.00
6	FRONT BUMPER AIR GUIDE GRILLE - LH / BR	1	\$	51.00
7	FRONT BUMPER CLOSING ELEMENT CENTRE - UPPER ?	1	\$	293.00
8	FRONT BUMPER AIR GUIDE GRILLE BLACK- LH ?	1	\$	151.00
9	FRONT BUMPER TRIM - LH ?	1	\$	54.00
10	RADIATOR GRILLE / BR	1	\$	1,754.00
11	FRONT BUMPER FOAM FILLER ? / BR	1	\$	212.00
12	FRONT BUMPER CARRIER ? / DO	1	\$	899.00
13	FRONT BUMPER BRACKET - LH / BR	1	\$	254.00
14	FRONT BUMPER GUIDE SECTION - LH / BR	1	\$	41.00
15	FRONT BUMPER TOP COVER / BR	1	\$	143.00
16	"CAUTION" SIGN STICKER / ne	1	\$	16.00
17	AIR CONDITIONER STICKER / ne	1	\$	9.00
18	FRONT BUMPER BRACKET / BR	1	\$	154.00
19	FRONT BUMPER SUPPORT LH RH ? / APC	2	\$	64.00
20	SIGNAL HORN HIGH TONE- LH ?	1	\$	134.00
SUB TOTAL SPARE PARTS		:	\$	7,590.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 7703 U

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	SPRING SHACKLE LH ?	1	\$	33.00	
22	FRONT BUMPER SENSOR FRONT - INNER X	1	\$	266.00	
23	FRONT BUMPER SENSOR FRONT - OUTER ?	1	\$	266.00	
24	FRONT SENSOR SEAL RING / Mc	4	\$	10.00	
25	FRONT FENDER - LH / DD	1	\$	1,227.00	
26	FRONT FENDER ATTACHMENTS PARTS ?	1	\$	225.00	
27	FRONT FENDER CLOSING ELEMENTS LH / BT	1	\$	81.00	
28	FRONT FENDER BRACKET - LH / BT	1	\$	41.00	
29	FRONT FENDER BRACE FRONT - LH ?	1	\$	132.00	
30	FRONT FENDER BRACKET DEFORMATION ELEMENT - LH X	1	\$	55.00	
31	FRONT FENDER BRACKET - LOWER LH / RH X	1	\$	36.00	
32	FRONT WHEEL HOUSING LINER - LH ?	1	\$	256.00	
33	FRONT WHEEL SPOILER UPPER - LH ?	1	\$	82.00	
34	FRONT WHEEL SPOILER LOWER - LH ?	1	\$	39.00	
35	FRONT BUMPER TOP COVER - LH / BR	1	\$	35.00	
36	FRONT HEADLAMP COVER - LH / BR	1	\$	49.00	
37	BONNET / DD	1	\$	3,425.00	
38	BONNET ATTACHMENTS PARTS X	1	\$	431.00	
39	BONNET LID HINGE LH / RH ?	2	\$	680.00	
40	BONNET IMPACT PROTECTION - CENTRE / Mc	1	\$	31.00	
SUB TOTAL SPARE PARTS			:	\$	7,400.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 7703 U

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	REFRIGERANT LINE SHORT	1	\$	186.00
62	REFRIGERANT LINE LONG	1	\$	381.00
63	REFRIGERANT LINE LOWER	1	\$	277.00
64	REFRIGERANT PIPE	1	\$	585.00
65	REFRIGERANT PIPE BRACKET	1	\$	9.00
66	COOLANT 1L	6	\$	297.00
67	FRONT AIR GUIDE OUTER - LH	1	\$	51.00
68	FRONT AIR GUIDE INNER - LH	1	\$	19.00
69	FRONT AIR GUIDE UPPER	1	\$	19.00
70	FRONT WINDOW SLOT SEAL - LH	1	\$	344.00
71	FRONT NO PLATE	S/N	\$	60.00
72	SUNDRIES	1	\$	400.00
TOTAL SPARE PARTS		:	\$	30,788.00
TOTAL LABOUR CHARGES		:	\$	11,582.00
GRAND TOTAL		:	\$	42,370.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55, UBI ROAD 1, SINGAPORE 408699
 TEL : 6368 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 7703 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING ATD.	S/N \$ 480.00	/
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	? /
4	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE.	S/N \$ 280.00	? X
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00	/
TOTAL LABOUR CHARGES		: \$ 2,790.00	