

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0888/2022/NK
DATE : 12-Oct-22
WIP : 45359

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS HAY YEE
ADDRESS : 19 JALAN AMPANG
SINGAPORE 268602

TELEPHONE : HP +65 96821202
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700012850-05
VEHICLE NO : SLD 7818 Z
MODEL CODE : AUDI A5 CAB 2.0 TFSI QU
MODEL YEAR : 31/5/2016
ENGINE NO : CNC 048413
CHASSIS NO : WAUZZZ8FXEN012562
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Oct-22
PLACE OF ACCIDENT : CARPARK EXIT B2 OF ARMENIAN ST

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLD 7818 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250 ✓
3	TO REMOVE AND RENEW AIR CON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$ 1,600.00	? ✗
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,000.00	1000 ✓
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDERS RHS FRONT FENDER TOP SUPPORT AND BONNET.	\$ 4,000.00	1650 ✓
TOTAL LABOUR CHARGES		: \$ 12,360.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLD 7818 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE/ POST WHEEL ALIGNMENT.	S/N \$	520.00	280 ✓
7	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,400.00	? ✗
8	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	X
9	TO CARRY OUT PRE / POST DIAGNOSTIC CHECK.	S/N \$	384.00	/ ✓
TOTAL LABOUR CHARGES		:	\$ 15,944.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 7B18 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER / DR	1	\$ 2,896.00	2316.80
2	FRONT BUMPER FIXING PARTS X nn	1	\$ 271.00	
3	FRONT BUMPER CLOSING ELEMENT LOWER - CENTER ? dm	1	\$ 254.00	138.48
4	FRONT BUMPER PULL STRAP LOWER / MS nn	3	\$ 174.00	X
5	FRONT BUMPER ENGINE UNDERSHIELD ? nn	1	\$ 134.00	X
6	FRONT BUMPER AIR GUIDE GRILLE - RH ? nn	1	\$ 254.00	X
7	RADIATOR GRILLE / DR	1	\$ 966.00	772.80
8	"QUATTRO" EMBLEM / MC	1	\$ 111.00	88.80
9	"QUATTRO" EMBLEM CLIP - MC	2	\$ 17.00	13.28
10	FRONT BUMPER WHEEL SPOILER FRONT - RH / CR4	1	\$ 66.00	52.80
11	FRONT BUMPER FOAM FILLER - DR	1	\$ 144.00	115.20
12	FRONT BUMPER REINFORCEMENT BEAM ? nn	1	\$ 985.00	X
13	FRONT BUMPER SUPPORT ? nn	2	\$ 29.00	X
14	FRONT BUMPER BRACKET - RH ? nn	1	\$ 255.00	X
15	FRONT BUMPER TOP COVER - EM DR	1	\$ 143.00	114
16	FRONT BUMPER GUIDE PC - BT	1	\$ 49.00	39.04
17	"CAUTION" SIGN STICKER / MC	1	\$ 16.00	12.40
18	AIRCONDITIONER STICKER X PK nn	1	\$ 34.00	X
19	SIGNAL HORN LOW TONE - RH ? nn	1	\$ 214.00	X
20	SPRING SHACKLE LOW TONE - RH ? nn	1	\$ 28.00	X
SUB TOTAL SPARE PARTS			\$	7,040.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 7818 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER - RH / OK	1	\$ 1,208.00	966.40
22	FRONT FENDER ATTACHMENTS PARTS X nn	1	\$ 60.00	
23	FRONT FENDER BRACE LOWER - RH ? bent	1	\$ 163.00	130.40
24	FRONT FENDER BRACKET FRONT / REAR - RH / ST	2	\$ 130.00	102.88
25	FRONT WHEEL HOUSING LINERS RH / CR4	1	\$ 197.00	157.60
26	FRONT WHEEL HOUSING LINERS ATTACHMENT PARTS ? nn	1	\$ 47.00	X
27	BONNET x R	1	\$ 3,491.00	
28	BONNET EDGE PROTECTION - FRONT / TN	1	\$ 31.00	24.72
29	BONNET CATCH HOOK X nn	1	\$ 155.00	
30	BONNET LID LOCK - FRONT X nn	1	\$ 228.00	
31	BONNET LOCK COVER V nn	1	\$ 26.00	
32	HEADLIGHT MOUNTING ? broken	1	\$ 138.00	110.40
33	HEADLIGHT BRACKETS - RH ? broken	1	\$ 118.00	94
34	HEADLIGHT - RH / OK	1	\$ 2,496.00	1996.80
35	HEADLIGHT HOSE - RH ? nn	1	\$ 42.00	X
36	HEADLIGHT GAS DISCHARGE LAMP ? nn	1	\$ 454.00	X
37	HEADLIGHT CONTROL UNIT ? nn	1	\$ 1,279.00	X
38	HEADLIGHT POWER MODULE FOR DAY DRIVING ? nn	1	\$ 635.00	X
39	HEADLIGHT LIFT CYCLINDER - RH / OK	1	\$ 292.00	233.60
40	HEADLIGHT LIFT CYCLINDER HOSE SM ? nn	1	\$ 204.00	X
SUB TOTAL SPARE PARTS			\$ 11,394.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 7818 Z

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	HEADLIGHT LIFY CYLINDER SECURING BRACKET RH ? nn	1	\$ 32.00	×
42	LOCK CARRIER ? nn	1	\$ 1,167.00	×
43	LOCK CARRIER BRACE ? nn	1	\$ 50.00	×
44	LOCK CARRIER SUPPORT ? nn	1	\$ 43.00	×
45	CHARGE AIR COOLER ? nn	1	\$ 628.00	×
46	PRESSURE HOSE- RH ? nn	1	\$ 466.00	×
47	AIR CON CONDENSER ? nn	1	\$ 816.00	×
48	AIR CON CONDENSER BRACKET ? nn	1	\$ 21.00	×
49	AIR CON CONDENSER AIR GUIDE RH ? nn	1	\$ 74.00	×
50	ALUMINIUM RIM / CV	1	\$ 1,458.00	1166.40
51	RUBBER VALVE / M	1	\$ 4.00	2.96
52	FRONT SUPPORT FRAME ? nn	1	\$ 4,322.00	×
53	FRONT WISHBONE LINK FRONT - RH ? nn	1	\$ 605.00	×
54	FRONT SUSPENSION GUIDE ? nn	1	\$ 1,120.00	×
55	FRONT LOWER ARM GUIDE - LOWER ? nn	1	\$ 605.00	×
56	FRONT LOWER ARM GUIDE - UPPER ? nn	1	\$ 605.00	×
57	FRONT WHEEL BEARING HOUSING ? nn	1	\$ 1,256.00	×
58	FRONT SWIVEL JOINT ? nn	1	\$ 214.00	×
59	FRONT WHEEL HUB ? nn	1	\$ 518.00	×
60	FRONT WHEEL BEARING ASSEMBLY ? nn	1	\$ 651.00	×
SUB TOTAL SPARE PARTS		:	\$ 14,655.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 7818 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT SUSPENSION FORKS RH <i>1 nn</i>	1	\$ 263.00	×
62	FRONT COUPLING ROD <i>1 nn</i>	2	\$ 258.00	×
63	FRONT SHOCK ABSORBERS <i>1 nn</i>	1	\$ 1,537.00	×
64	FRONT TRACK ROD <i>1 nn</i>	1	\$ 109.00	×
65	TIE ROD END- RH <i>1 nn</i>	1	\$ 195.00	×
66	FRONT NO PLATE <i>9 / npc</i>	S/N	\$ 60.00	60
67	FRONT TYRE - RHS <i>1 / TN</i>	1	TBC 410	
68	SUNDRIES <i>1 / nec</i>	1	\$ 700.00	23.84
TOTAL SPARE PARTS		:	\$ 36,211.00	
TOTAL LABOUR CHARGES		:	\$ 15,944.00	
GRAND TOTAL		:	\$ 52,155.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Steve (LKK)
 SURVEYED DATE : 18/10/22, 2.22pm
 AUTHORISED DATE :
 EXCESS COST : 90-M AL
 LIABILITY :
 REMARKS : Excess-?
 PIP, 6 days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT