

TCPK ENTERPRISE

Blk5033 Ang Mo Kio Industrial Park 2 #01-267

S'pore 569536

Email: tcpk.sg@gmail.com

PAYNOW UEN: 53386481W

KK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date 25/10/2022

Your Ref: SH9459J

Our Ref: DC20221013SMN6219U

Vehicle No.: SMN6219U

Accident Date: 13/10/2022

To Insurance Co: TOKIO MARINE INSURANCE (S) LTD

Model: HONDA JAZZ

RE: ESTIMATED COST FOR REPAIR VEHICLE NO. SMN6219U.

		Recommended Part(S)	Repairer's
No.	Qty	Description	
1	1	Rear bumper <i>de</i>	\$ 494.60
2	2	Rear bumper retainers <i>nee</i>	\$ 112.40
3	4	Rear bumper clips <i>ne</i>	\$ 14.00
4	1	Rear bumper centre moulding <i>de</i>	\$ 85.00
5	2	Rear bumper side moulding <i>X 11</i>	\$ 170.00 <i>X</i>
6	2	Rear bumper side garnishes <i>X 11</i>	\$ 78.00 <i>X</i>
7	1	Rear end panel <i>bt</i>	\$ 495.00
8	1	Rear end panel top garnish <i>de</i>	\$ 105.00
9	1	Rear end panel inner storage garnish <i>de</i>	\$ 380.80
10	1	Rear tailgate lid <i>bt</i>	\$ 716.30
11	1	Rear tailgate rubber <i>ne</i>	\$ 95.00
12	1	Rear tailgate lock <i>cut</i>	\$ 84.00
13	1	Rear tailgate inner trim board <i>de</i>	\$ 350.00
14	1	Rear tailgate "Jazz" emblem <i>ne</i>	\$ 45.00
15	1	Rear tailgate centre garnish <i>X 11</i>	\$ 270.00 <i>X</i>
16	1	Rear tailgate centre emblem <i>X 11</i>	\$ 58.00 <i>X</i>
17	2	Rear number plate lamps <i>X 11</i>	\$ 44.00 <i>X</i>
18	2	Rear taillamps <i>sur - 1PC (RH)</i>	\$ 944.00 <i>472</i>
19	1	Rear tailgate inner pocket <i>X 11</i>	\$ 39.00 <i>X</i>
20	1	Rear fenders (R) <i>repair</i>	\$ 460.00 <i>X 11</i>
21	1	Rear floor panel <i>repair</i>	\$ 286.00 <i>X 11</i>
All			\$5,326.10
Less 20%			\$1,065.22
(A) Parts Total			\$4,260.88

3449.10
20%
2759.28

TCPK ENTERPRISE

Blk5033 Ang Mo Kio Industrial Park 2 #01-267

S'pore 569536

Email: tcpk.sg@gmail.com PAYNOW UEN: 53386481W

Date 25/10/2022
Your Ref: SH9459J
Our Ref: DC20221013SMN6219U

Vehicle No.: SMN6219U

2759.28
320.00
2210.00
5289.28
202
4231.42

HS-\$4,200/7days

<u>S/Nett</u>			
1	1	Reae tailgate w/screen moulding <i>an</i>	\$ 150.00 <i>60</i>
2	1	Reae w/screen sealant <i>an</i>	\$ 100.00 <i>40</i>
3	1	Rear number plate with casing <i>X an</i>	\$ 60.00 <i>X</i>
4	1	Rear reverse camera <i>X an</i>	\$ 480.00 <i>X</i>
5	2	Rear reverse sensor <i>an</i>	\$ 180.00 <i>✓</i>
6	1	Panel sealant <i>an</i>	\$ 80.00 <i>40</i>

(B) S/Nett Parts Total \$ 1,050.00 *320*

Labour Charges:

To wiring.	<i>Panel</i>	\$ 50.00 <i>30</i>
To remove and refit rear w/screen glass.	<i>4p 900/10068</i>	\$ 150.00 <i>120</i>
To transfer new boot lid parts to new one.	<i>7 days</i>	\$ 80.00 <i>60</i>
To remove and repair exhaust pipe	<i>4/3</i>	\$ 80.00 <i>X an</i>
To install reverse camera and testing for functioning.	<i>19/10/22 @ 1130</i>	\$ 80.00 <i>40</i>
Labour charge for repair and panel beating, cut/weld and replac the above damaged parts.	<i>Resin after repair</i>	\$ 1,200.00 <i>900</i>
To putty, apply primer & spray painting		\$ 1,200.00 <i>1000</i>
To apply rust proofing on the repaired/replaced panels.		\$ 150.00 <i>60</i>

(C) labour Total \$ 2,990.00 *2210*

Repair Cost Gross Total	\$8,300.88
-------------------------	------------