



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LIBERTY INSURANCE PTE LTD  
51 CLUB STREET, #03-00  
LIBERTY HOUSESINGAPORE 069428

Ref: CS/LIP22010370/Uvy3m4

Date: 24/11/2022

Code: LIP

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	YQ 6080T	<b>Veh. Inspected</b>	YQ 360A
<b>Policy No.</b>	SD22V11812/VCV/R00	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	AVS22/2945	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	TED SEAH	<b>Assign Date</b>	18/10/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MITSUBISHI CANTER FEB21 (M)	<b>c.c</b>	2998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	-
<b>Chassis No.</b>	FEB21EA30099	<b>Colour</b>	WHITE
<b>Odometer</b>	30854 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/85 R15	DUNLOP	6 mm
<b>L/H Front Tyre</b>	195/85 R15	DUNLOP	6 mm
<b>R/H Rear Tyre</b>	195/85 R15 (D/D)	YOKOHAMA	6/6 mm
<b>L/H Rear Tyre</b>	195/85 R15 (D/D)	YOKOHAMA	6/6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	14/10/2022	<b>Inspection Date</b>	20/10/2022
<b>Survey held at</b>	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278		

### 5a. Remarks

A)REGISTRATION DATE: 13 MARCH 2019  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>2 Working Days</b>
--	-----------------------