

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLF 9383L Yr Regn: 21/1/15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW M3 c.o. 1999Colour: Blue A/C: Insured / Std / HI / NASp. Reading: 86190 T/Radio: Insured / Std / HI / NA

Eng/No: _____

C/No: WBS3C970XDP818017

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 285/30ZR20R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front

Rear

R/Bal. 4 mm R/Bal. 4 mmU/Bal. 4 mm U/Bal. 4 mmD.O.A. 10/10/92 D.O.I. 19/10/92Survey held at PerformanceDes. of Damages: Frt / Rear / O/S / N/S / UIC / Roof or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-148K

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.E. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Ster (LKK)

19/10/22, 12.30P

DD-MI AL

EXA, -?

16 Lys

M B L Y

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 63729		Page No. : 1 of 5	
Date Estimated : 18/10/2022			
Prepared By : Inthiran A/L Thurasamy			
- ESTIMATE REPAIR FOR - Cho Wei Hao (Zhu WeiHao) 8 Dover Rise #16-02 Singapore 138679		- ACCOUNT - 224093 Allianz Insurance Singapore Pte Ltd 79 Robinson Road #09-01 Singapore 068897	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLF9383L	WBS3C920X0P818017	02/01/2015	F80 M3 LIM	0

DESCRIPTION	VALUE
To replace rear rh fender, front bumper, make good of rear bumper, bootlid and bonnet including knocking and pulling of c pillar. I	7225 10,200.00
To painting rear rh fender, rear bumper, boot lid, roof frame, c pillar, bonnet and front bumper.	6228 6,346.00
To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.	280 295.00
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repair. (phat)	829 873.00
To replace rear windscreen glass.	574.00 ✓
To conduct water leak tests.	75.00 ✓
To supply and install front or rear windscreen solar film.	531.00 ✓
To remove and install fuse box at the rear section to facilitate repair. (phat)	534 531.00
To carry out body cavity preservation. (For cut panel).	534 531.00
Sundries.	150.00 ✓
To supply front emboss number plate.	150.00 ✓
To replace left or right headlight.	457 481.00
Total Labour 1:	20,737.00



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 63729
Date Estimated : 18/10/2022
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLF9383L	WBS3C920X0P818017	02/01/2015	F80 M3 LIM	0

DESCRIPTION	QTY	PRIC	VALUE
BLIND PLUG ✓ n/c	3	1.05	3.15
REAR RH SIDE PANEL - DO ✓	1	2,011.50	2,011.50
RH C-PILLAR REINFORCEMENT PLATE ✓ n/c	1	54.55	54.55
RH SILL REINFORCEMENT PLATE ✓ n/c	1	54.55	54.55
T WELD BOLT L=5.4MM ✓ n/c	15	0.90	13.50
COVER REGISTRATION PLATE (ECE) ✓ BR	1	99.35	99.35
FRT BUMPER PANEL PRIMED (SRA) ✓ BR	1	1,410.05	1,410.05
FRT BUMPER REPAIR KIT HOLDER ✓	1	87.75	87.75
RIGHT PROTEC ✓ n/c	1	13.05	13.05
(S/L) RH WHEEL ARCH PROTECTIVE FILM ✓ n/c	1	91.45	91.45
REAR WINDOW ✓ BR	1	706.10	706.10
Cover (H) ✓ ?	1	83.55	83.55
Cover c pillar ✓ CVT	1	83.55	83.55
BLIND RIVET NUT ✓ n/c	1	4.85	4.85
M PERFORMANCE FRT RH GRILLE BLK ✓ BR	1	294.85	294.85
M PERFORMANCE FRT LH GRILLE (BLACK) ✓ ?	1	294.85	294.85
RH HEADLIGHT LED AHL ✓ - BR	1	3,135.20	3,135.20
REAR RH LIGHT IN THE SIDE PANEL ✓ ?	1	397.90	397.90
REAR RH LIGHT IN TRUNK LID ✓ ?	1	278.55	278.55
THIRD STOPLAMP - BR ✓	1	334.60	334.60
FIXING KIT CLIPS ✓ n/c	1	17.30	17.30
BLIND RIVET HEMLOCK 813 ✓ n/c	3	2.65	7.95
BLIND RIVET AVIBVLB ✓ n/c	15	0.55	8.25
SCREW (SF PLUS M5X15) ✓ n/c	5	0.60	3.00
(DG) BODYWORK ADHESIVE K5A (50ML) ✓ n/c	1	121.90	121.90
(DG) CLEANER R1 (100ML) ✓ n/c	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) ✓ n/c	2	131.55	263.10
PUNCH RIVET N4 ✓ n/c	50	0.55	27.50
(DG/SL) ADHESIVE SET K6 ✓ n/c	1	53.05	53.05
(DG/SL) BODY ADHESIVE K5 (195 ML) ✓ n/c	1	353.50	353.50
(SL/DG) SEALANT D2 290ML ✓ n/c	1	32.10	32.10

Total Parts : 10,366.70

LKK Auto Consultants hereby notify

the Repairer of the following:

To survey before/after spray painting

to replace damaged part(s) during resurvey

All prices are subject to confirmation

The survey is on a "Without Prejudice" basis

No legal modification(s) is allowed

Any supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company



Labour 1	:	20,737.00
Parts	:	10,366.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,177.26
Grand Total	:	33,280.96

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **

Date: