

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

MVA: Loke Wei Yiang

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	18/10/2022
Vehicle Reg. No.:	SH9408G	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	02/04/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU192066	Chassis No:	KMHC851CVKU141569
Odometer:	426607 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,658.12
Miscellaneous Items	11.00
Labour	1,330.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,999.12
+ GST 7.00% (S\$)	209.94
Nett Amount (S\$)	3,209.06

This claim is handled by: MS. LOKE YY

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Oct 2022)
Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SH9408G/18/10/2022 14:37
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER / ll	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER CLIPS / ll	20.00	0.00	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY / OAA	20.00	0.00	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT ?	20.00	0.00	*394.80 FL
5	1		*REAR BUMPER LWR CTR MOULDING X NN ?	20.00	0.00	*155.00 FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET LH ?	20.00	0.00	*148.10 FL
7	1		*REAR BUMPER SIDE BRACKET LH ?	20.00	0.00	*55.80 FL
8	1		*REAR BUMPER TOWING COVER / cut	20.00	0.00	*98.80 FL
9	1		*REAR BUMPER RUBBER MAT / ll	0.00	0.00	*50.00 F
10	1		*REAR BUMPER REVERSE SENSOR / cut	0.00	0.00	*180.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,015.15
- List Item Discount on L Items (S\$)	357.03
Total Parts (S\$)	1,658.12

ComfortDelGro Engineering Pte Ltd/SH9408G/18/10/2022 14:37. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	RENEW ADVERTISEMENT STICKER	New	200.00
2	PANEL BEATING	New	750.00
3	SPRAY PAINTING CHARGE	New	300.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00
Gross Labour Cost (S\$)			1,330.00

250
250
40

ComfortDelGro Engineering Pte Ltd/SH9408G/18/10/2022 14:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2 Days.
45
Gene Of
19/10
4pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on "Without Prejudice" basis
- No illegal activities to be carried out
- Supply and installation of parts and labour is subject to final approval from insurance company

Acknowledged by Repairer
Signature:
Date: