

原摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SMJ7322T

No.	Qty	List Items		
1	1	Front bumper 1050	\$ Bu 1,050.00	—
2	2	Rear bumper side retainer	\$ CM 244.00	✓
3	2	Front bumper corner retainer	\$ Su 86.00	X
4	1 set	Rear bumper clips	\$ Su 40.00	—
5	1	Rear bumper inner reinforcement	\$ Bu 320.00	✓
6	1	Front grille 395	\$ CM 395.00	✓
7	1	Front grille upper chrome	\$ Su 365.50	X
8	1	Front grille lower chrome 231	\$ CM 280.70	✓
9	1	Front grille centre "H" logo	\$ Su 72.40	✓
10	2	Headlamp @ 2250 NLS My CM	\$ Su 4,500.00	X
11	2	Headlamp top chrome	\$ Su 426.00	X
12	2	Headlamp lower bracket @ 116.00 NLS CM	\$ Su 440.00	X
			\$ 8,219.60	
			Less 20%	\$ 1,643.92
			Total :	\$ 6,575.68

Special Nett Items

13	1	Front number plate	\$ Su 50.00	X
----	---	--------------------	-------------	---

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 600.00	250
2	To putty and spray Spray Paintings charges.	\$ 600.00	220
3	To check wirings and lightings.	\$ 40.00	150
4	To supply and apply anti rust treatment	\$ 50.00	X
		Total :	\$ 1,290.00

Total Parts and Labour : \$ 7,915.68

Not Withain
Recovery B4pain

3 day

61 Sng @ 3400h

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: