

Date: 18/10/2022
Vehicle No: SLR8987M
Model: TOYOTA PRIUS 1.8E HYBRID
Chassis: ZVW518038653 - 2017
Reg.Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SMP4035K
Date of Accident: 15/10/2022
Estimator: KIT
Surveyor:

Not Authorised
1/10/22
Recovery After Pain
2-3 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>Bu</i> \$488.50
2	REAR BUMPER SIDE RETAINER LH	1		<i>Bu</i> \$112.60
3	REAR BUMPER SIDE RETAINER RH	1		\$112.60
4	REAR BUMPER LOWER GARNISH	1		<i>Re</i> \$576.80
5	REAR BUMPER TOWING COVER	1		<i>Bu</i> \$54.80
6	REAR BUMPER ANTENNA SENSOR	1		\$78.50
7	REAR BUMPER REINFORCEMENT	1		\$336.20
8	REAR END PANEL TOP GARNISH	1		<i>Bu</i> \$155.90
9	REAR END PANEL	1		REPAIR
10	REAR TAILGATE OUTER GARNISH	1		REPAIR
SUB TOTAL				\$1,915.90
LESS 25%				\$478.98
PARTS TOTAL				\$1,436.93

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>Re</i> \$50.00
2	REAR BUMPER REVERSE SENSOR	1		\$300.00
3	REAR END PANEL TOP GARNISH CLIPS	1		<i>Re</i> \$30.00
S/N TOTAL				\$380.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS. \$500.00 *250*

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. \$500.00 *220*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. \$100.00 *50*

TO TUFF KOTE & UNDERSEAL MATERIALS. *Re* \$80.00 *X*

TO DIAGNOSIS FAULT CODE & RESET MEMORY. \$80.00 *?*

LABOUR TOTAL \$1,260.00

KIT TOTAL \$3,076.93

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1393

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

