

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 18 Apr 2023

Preliminary Advice

Vehicle No	: SMV3731J	Accident Date	: 07/09/2022
Make	: M.G. HS	Policy No.	: DMPCSNW00185362100
Assignment Date	: 18/10/2022	Excess	: S\$3,750.00
Date of Inspection	: 19/10/2022	Est. Duration of Repair	: 7
Inspection At	: SAT (SG) PTE. LTD (HQ) 8 KAKI BUKIT AVE 4 #03-41/03/42 PREMIER@KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,867.73
Revised Amount	:S\$	11,368.43
Check Items (Estimated)	:S\$	3,703.00
Total	:S\$	15,071.43
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	44,552.00
Salvage Value	:S\$	
Margin for Repair	:S\$	75,448.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.