

ASS. REC. BY: T. J. J. H.REF: CS/CT 220/0390/Ty3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 3750

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 9120K.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMV373/5 Yr Regn: 2020 1 Sep.Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MG HS 1.5 c.c. 1490.Colour: Black. A/C: Insured / Std / NI / NASp. Reading: 59521 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LSJA24493LA029240.Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: 235/50R18R: 235/50R18BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 19/10/22Survey held at SAT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: _____

Lump Sum / L.B. (\$)

SAT (SG) PTE LTD

61 Ubi Road 1 #04-14 Oxley Bizhub Singapore 408727

TEL: 6242 2212 FAX: 62426169

Vehicle No: SMV3731J

Model No. M.G

Chassis no. LSJA24

Accident Date : 08.09.2022

Owner : Yeo Quek Khim

Date of Estimate : 16/09/2022

Estimate for Accident Vehicle No. SMV3731J

<u>List Items:</u>	Qty	Unit Price	Total Amount
1 Rear bumper upper	1	\$782.40	\$782.40 de ✓
2 Rear bumper lower	1	\$498.00	\$498.00 de ✓
3 Rear bumper lower spoiler	1	\$282.00	\$282.00 de ✓
4 Rear bumper reinforcement	1	\$580.00	\$580.00 ?
5 Rear bumper side retainer	2 RHX	\$25.00	\$50.00 LH de ✓
6 Rear bumper clips (Set)	1	\$50.00	\$50.00 ne ✓
7 Rear bumper reverse sensor	1 ✓	\$348.00	\$1,392.00 mis ✓
8 Rear end panel	1	\$154.00	\$154.00 R ✓
9 Rear fog lamp lh	1	\$154.80	\$154.80 Cna ✓
10 Tailgate	1	\$3,240.00	\$3,240.00 bf ✓
11 Tailgate lamp lh	1	\$630.00	\$630.00 Cna ✓
12 Tailgate logo	1	\$45.00	\$45.00 ne ✓
13 Tailgate weatherstrip	1	\$125.00	\$125.00 X
14 Tailgate inner trim	1	\$105.00	\$105.00 X
15 Tailgate windscreen glass moulding	1	\$38.00	\$38.00 ne ✓
16 Tailgate windscreen glass sealant	1	\$27.00	\$27.00 ne ✓
17 Taillamp lh	1	\$1,104.00	\$1,104.00 Cna ✓
18 Taillamp panel lh	1	\$93.00	\$93.00 R ✓
19 Rear fender arch garnish	2	\$115.00	\$230.00 X
20 Rear exhaust silencer	1	\$2,640.00	\$2,640.00 ?
21 Rear number plate	1	\$30.00	\$30.00 X
Sub-Total Amount =			\$10,969.80
Add 15%			\$1,645.47
Sub-Total =			\$12,615.27

Labour charges

1 Panel beating for replace and repair affected parts	\$1,400.00 700
2 Spray painting	\$1,500.00 750
3 Apply putty and anti-corrosion to affected parts.	\$100.00 40
4 Wiring / bulb checking	\$50.00 40

5	Transfer tailgate mechanisms	\$150.00	60.
6	Remove & refix tailgate windscreen glass	\$200.00	120
7	Remove & refix rear bumper reverse sensor	\$100.00	50
8	Remove & refix rear exhaust silencer	\$280.00	100.
		<u>\$3,780.00</u>	

Total parts	=	\$12,615.27
Total labour	=	\$3,780.00
Total Amount	=	<u>\$16,395.27</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjin 97495749

Not authorise Ex \$3750

19/10/22 @ 4pm.

6-7 days.

Tanjin C (LKK Auto - Wm)