



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SLQ8531A
Chassis No : JHMRU1830GX202667
Model : HRV LX-SIN CVT YM 2016
Owner's Name : MAUNG HTIN ZAW SOE
Ins Policy No. :
Date of Accident : 15/10/2022

Document No. : SQT22003060
Date : 18. Oct 2022
Customer No. : WZC008
Svc Advisor : LEE CHEN SIN
Engine No : L15B4532667
Date | Time : 18. Oct 2022 3:44:51 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:MAUNG HTINZAW SOE OWNER INSURER: TOKIO MARINE ACC DATE: 15/10/2022 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: SND1605L						
68100-T7A-J20ZZ	TAIL GATE COMP ✓	1	915.90	25	686.92	48.08	735.00
74800-T7A-J02	LOCK ASSYTAILGATE X n	1	91.10	25	68.32	4.78	73.10
74440-T7A-003	WEATHERSTRIPTAILGATE X n	1	105.60	25	79.20	5.54	84.74
74827-SWA-A10	STOPPERTAILGATE n /	1	4.10	25	6.15	0.43	6.58
75722-T7W-A01	EMBLEMRR. n /	1	15.40	25	11.55	0.81	12.36
75725-T8N-T00	EMBLEM,RR. I-VTEC n /	1	16.70	25	12.52	0.88	13.40
73211-T8N-T02	GLASS SET,RR.WINDSHIELD ? X n	1	739.80	25	554.85	38.84	593.69
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER n /	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 n /	1	9.10	25	6.82	0.48	7.30
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER n /	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPVOT n /	1	5.20	25	3.90	0.27	4.17
91501-S70-003	FASTENER BW/SHIELD n /	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B n /	2	5.40	25	8.10	0.57	8.67
91536-SS0-J01	FASTENER AW/SHIELD n /	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N) n /	2	60.00		120.00	8.40	128.40
33552-T7A-J01	LAMP UNITL. X n	1	509.60	25	382.20	26.75	408.95
04718-T7A-000ZZ	FACEL,RR.BUMPER CORNER sun /	1	103.80	25	77.85	5.45	83.30
71598-T7A-J00	SPACER,L,RR.BPR S n /	1	18.10	25	13.57	0.95	14.52
04715-T7A-900ZZ	FACE,RR.BUMPER turn /	1	484.70	25	363.52	25.45	388.97

Printed on 18/10/2022 3:59:47 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

HONDA

KAH MOTOR CO. SDN. BHD.

Member of the Oriental Holdings Berhad)
and Body Repair

65 6841 3838

Website: www.honda.com.sg

24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SLQ8531A
Chassis No : JHMRU1830GX202667
Model : HRV LX-SIN CVT YM 2016
Owner's Name : MAUNG HTIN ZAW SOE
Ins Policy No :
Date of Accident : 15/10/2022

Document No. : SQT22003060
Date : 18. Oct 2022
Customer No. : WZC008
Svc Advisor : LEE CHEN SIN
Engine No : L15B4532667
Date | Time : 18. Oct 2022 3:44:51 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incl GST
33555-T7A-J01	REFLECTOR ASSYL.RR. <i>sc</i>	1	180.40	25	135.30	9.47	144.77
91505-TM8-003	CLIP,BUMPER <i>w</i>	10	2.30	25	17.25	1.21	18.46
66100-T7A-300ZZ	PANEL COMPRR. <i>repair</i>	1	399.40	25	299.55	20.97	320.52
84640-T7A-J01ZA	LINING ASSYRR.PANEL <i>Xan</i>	1	47.00	25	35.25	2.47	37.72
84660-T7A-J02ZA	BASE COMP,L.TRUNK SIDE LINING <i>Xan</i>	1	145.40	25	109.05	7.63	116.68
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>sc</i>	1	320.00		320.00	22.40	342.40
Sum Item					3362.41	235.36	3597.77
BG02R	REPLACE RR. WINDSCREEN.(N) <i>Remove</i>	1	650.00		650.00	45.50	695.50
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00	180	280.00	19.60	299.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	600.00	50	600.00	42.00	642.00
BC011R	REMOVE, INSTALL & CALIBRATE REAR VIEW CAMERA	1	600.00	50	600.00	42.00	642.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	325	650.00	45.50	695.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	350.00	200	350.00	24.50	374.50
BOJSE	END PANEL SEALANT	1	80.00	Xan	80.00	5.60	85.60
BOBC	BODY UNDERSIDE COATING (N)	1	350.00	Xan	350.00	24.50	374.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	4550.00	1950	4550.00	318.50	4868.50
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)	1	3640.00	1820	3640.00	254.80	3894.80
Sum Labor					12500.00	875.00	13375.00
BO-VK-ASTRO-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN	1	300.00	Xan	300.00	21.00	321.00
Sum Ext. Service					300.00	21.00	321.00

Survey By

Printed on 18/10/2022 3:59:47 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

HONDA**KAH MOTOR CO. SDN. BHD.**

(a subsidiary of the Oriental Holdings Berhad)

Body Repair

847 3838

24hrs Roadside Assistance, Call 98203838

Website: www.honda.com.sg

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Registration No

Chassis No

Model

Owner's Name

Ins Policy No.

Date of Accident

: CHINA TAIPING INSURANCE (S'PORE) PTE

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

: SLQ8531A

: JHMRU1830GX202667

: HRV LX-SIN CVT YM 2016

: MAUNG HTIN ZAW SOE

:

: 15/10/2022

Document No.

: SQT22003060

Page 3

Date

: 18. Oct 2022

Customer No.

: WZC008

Svc Advisor

: LEE CHEN SIN

Engine No

: L15B4532667

Date | Time

: 18. Oct 2022 3:44:51 PM

Surveyor Name

:

Survey Date

:

Authorisation Date

:

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
Date & Time	31/10/22 @ 1100						
Excess							
Status							
Signature							

Total Amount

16,162.41

1,131.36

17,293.77

Total (Inclusive of GST)

17,293.77

Repair
Hq 90010568
6 days
Resy before print

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sign

Date

Printed on 18/10/2022 3:59:47 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.