

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22010397/GPA3Q2**Date:** 18/05/2023REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2000587163-01
Claimant Vehicle No : YQ1582U **Insured Vehicle No :** SLF1188L
 Date of Loss: 08/09/2022 Nature of Claim: TP Claim No: 202222006605SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YQ1582U**
 Make & Model: HINO XZU710R, 4.0 D 14FT WIDE CAB 5T (M) Engine No: N04CVV10976
 Reg. Date: 27/11/2019 (Man. Year: 2019) Chassis No: JHHUCV3H60K032962
 Colour: White Odometer: 152909 km
 Engine Capacity: 4009 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00 R16 Rear Tyre Size: 7.00 R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,438.00	2,075.00	363.00	14.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	650.00	410.00	38.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,498.00	2,725.00	773.00	22.10
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	3,498.00	2,200.00	1,298.00	37.11
+ GST 7.00/8.00% (S\$)	244.86	176.00	68.86	28.12
Nett Amount (S\$)	3,742.86	2,376.00	1,366.86	36.52
+ Loss of Use (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,858.00		

INSPECTION

Date of Assignment: 20/10/2022 Present Location: Vin's Motor Pte Ltd (Sin Ming)
 Date Inspected: 20/10/2022 Inspected At: Vin's Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive, #03-03, Sin Ming AutoCity
 Singapore 575722
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 May 2023)	
Parts:	N/A	HINO XZU710R 4.0 D 14FT WIDE CAB 5T (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ1582U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*TAILLAMP (WCP)	Cut	300.00 F	*300.00 F
2	1		*REAR STEP (WOODEN) (WCP)	Cracked	480.00 F	*450.00 F
3	1		*REAR IRON BAR (WCP)	Bent	850.00 F	*800.00 F
4	2		*REAR IRON BAR BRACKET (WCP)	Bent (1 PCS ONLY)	440.00 F	*220.00 F
5	1		*REAR NUMBER PLATE LAMP (WCP)	Distorted	110.00 F	*80.00 F
6	1		*REAR NUMBER PLATE	Cut	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,220.00	1,890.00
+ Margin on L,N Items 10.00/10.00% (S\$)	218.00	185.00
Total Parts (S\$)	2,438.00	2,075.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR DAMAGES	New	580.00	300.00
2	TO SPRAY PAINTING	New	480.00	350.00
Gross Labour Cost (S\$)			1,060.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >