

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Claim Details

Case Ref. No. : TP/092022/5627
Date : 09-09-2022
Accident Date : 08-09-2022

Vehicle Details

Make & Model : Hino XZU710R 14FT WIDE CAB 5T
Chassis No : JHHUCV3H60K032962
Registration No : YQ1582U

Third Party Vehicle Details

Registration No : SLF1188L

S/N	Description	Qty	Amount (\$)
1	TAILLAMP / cut	2.00	\$300.00
2	REAR STEP (WOODEN) / CAA	1.00	\$480.00
3	REAR IRON BAR / BT	1.00	\$850.00 800(SN)
4	REAR NUMBER PLATE / REAR IRON BAR BRACKET / BT	1.200	\$440.00 220(SN)
5	REAR NUMBER PLATE LAMP / BT	1.00	\$110.00
			\$2,180.00
Margin: 10%			\$218.00
			\$2,398.00
6	REAR NUMBER PLATE / CA	1.00	\$40.00
7	TO REPAIR DAMAGES	1.00	\$580.00
8	TO SPRAY PAINTING	1.00	\$480.00
Subtotal w/o GST:			\$3,498.00

3 Days.
4/5
6m Aug
20/10

LKK Auto Consultants hence notify the Repairer of the following:

- To restore the vehicle to its original condition.
- To do the necessary repairs to the vehicle.
- To do the necessary repairs to the vehicle.
- To do the necessary repairs to the vehicle.
- To do the necessary repairs to the vehicle.
- To do the necessary repairs to the vehicle.
- To do the necessary repairs to the vehicle.
- To do the necessary repairs to the vehicle.

Acknowledged by Repairer

Signature:

Date:

Issued by Iswan

This is a computer-generated document. No signature is required.