

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Claim Details

Case Ref. No. : TP/092022/5627
Date : 09-09-2022
Accident Date : 08-09-2022

Vehicle Details

Make & Model : Hino XZU710R 14FT WIDE CAB 5T
Chassis No : JHHUCV3H60K032962
Registration No : YQ1582U

Third Party Vehicle Details

Registration No : SLF1188L

S/N	Description	Qty	Amount (\$)
1	TAILLAMP <i>- Cat</i>	2.00	\$300.00 ✓
2	REAR STEP (WOODEN) <i>- CAA</i>	1.00	\$480.00 450 ✓
3	REAR IRON BAR <i>- BT</i>	1.00	\$850.00 800
4	REAR NUMBER PLATE REAR IRON BAR BRACKET <i>- BT</i>	1.00 2.00	\$440.00 220
5	REAR NUMBER PLATE LAMP <i>- BT</i>	1.00	\$110.00 80 ✓
			\$2,180.00
			1850 +10% 2035
			Margin: 10%
			\$218.00
			\$2,398.00
6	REAR NUMBER PLATE <i>- CA</i>	1.00	\$40.00 ✓
7	TO REPAIR DAMAGES	1.00	\$580.00 300
8	TO SPRAY PAINTING	1.00	\$480.00 350
			690
Subtotal w/o GST:			\$3,498.00

3 Days.
L/S
Gme Ar
20/10

2752

L/S - 2180
= 2200

LKK Auto Consultants hence notify the Repairer of the following:

- To reserve a fee for spray painting.
- To do a repair on the rear number plate.
- To do a repair on the rear iron bar.
- To do a repair on the rear number plate lamp.
- To do a repair on the rear number plate bracket.
- To do a repair on the rear number plate.
- To do a repair on the rear number plate.
- To do a repair on the rear number plate.

Acknowledged by Repairer

Signature:

Date:

Issued by Iswan

This is a computer-generated document. No signature is required.