

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte.
Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 20 Oct 2022

Preliminary Advice

Vehicle No	: SJY1726H	Accident Date	: 15/10/2022
Make	: TOYOTA WISH	Policy No.	: P000010884
Assignment Date	: 19/10/2022	Excess	: S\$2,000.00
Date of Inspection	: 20/10/2022	Est. Duration of Repair	: 5
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,687.00
Revised Amount	:S\$	3,486.00
Check Items (Estimated)	:S\$	1,881.00
Total	:S\$	5,367.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	26,114.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,886.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on Lump Sum basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.