



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722  
 Mobile: 9688-0413 Fax: 6266-7396  
 Email: absolute.app.svcs@gmail.com

Vehicle No: PA87E

Report No: AAS/2021/030

**Appraisement Schedule**

S/N	Parts Description	Qty	Condition	Repairer's Est	Revised Est
1	Front bumper	1	Grazed/Cracked	\$ 1,225.00	\$ 1,225.00 ✓
2	Front bumper fog lamp RH	1	Refit	\$ 223.00	-
3	Headlamp assy	1set	RH Grazed/Cut	\$ 1,774.00	\$ 1,774.00 <b>1188.92</b>
4	RHF quarter panel		Dented/Repair	-	-
			<b>2413.92</b>		
			<b>10%</b>		
			<b>2172.52</b>		
			Total:	\$ 3,222.00	\$ 2,999.00
			-10%	\$ 322.20	\$ 299.90
			List total:	\$ 2,899.80	\$ 2,699.10

S/N	Labour Description	Repairer's Est	Revised Est
1	To check lightings & wirings.	\$ 50.00	\$ 30.00 ✓
2	To replace damaged parts/panels. Conduct cutting, welding, straightening, & panel beating on affected area. Re-align all affected areas.	\$ 800.00	\$ 450.00 <b>400</b>
3	To putty, grind smoothen & respray replacement & affected panels. (3 tone with design)	\$ 1,000.00	\$ 600.00 <b>200</b>
4	Anti rust on affected panels.	\$ 100.00	\$ 40.00 ✓
		<b>670</b>	
		Labour Total:	\$ 1,950.00
			\$ 1,120.00
		Grand Total:	\$ 4,849.80
			\$ 3,819.10

The final adjusted lump sum amount is \$3,050.00

Under normal circumstances, the repair should be completed within a reasonable period of 4 working days.

19 Photographs were taken at the time of inspection.

**2172.52**  
**670.00**  


---

**2842.52**  
**20%**  
**2274.02**  
**L/S-\$2,250/3DAYS**

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.

Photo Submitted	YES / NO	Date of submission
-----------------	----------	--------------------