

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: HL Assurance Pte Ltd  
11 Keppel Road  
#11-01 ABI Plaza  
Singapore 089057

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Joel Goh Zan Wei

Date: 15 Nov 2022

## **Preliminary Advice**

Insured	: SLB9090C		
Vehicle No			
TP Vehicle No	: SHC3257X	Accident Date	: 17/10/2022
Make	: HYUNDAI AE IONIQ	Assignment Date	: 19/10/2022
Date of Inspection	: 19/10/2022	Est. Duration of Repair	: 7
Inspection At	: BIFROST AUTO PTE LTD (HQ) 176 SIN MING DRIVE, #03-09 SINGAPORE 575721		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,007.45
Revised Amount	:S\$	13,090.51
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,090.51

Lump Sum Repair	:S\$
-----------------	------

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$

Margin for Repair

:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.