



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|-------------------------------------|----------------------------|----------------|
| SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 | | | Ref: CS/SMO22010402/Kvy3q2 | |
| | | | Date: 09/11/2022 | |
| | | | Code: SMO | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | GBD 5246E | Veh. Inspected | PC 5479P |
| | Policy No. | D21MTPCVE002689 | Coverage (\$) | 0.00 |
| | Claim No. | CMTD2203796/GPL | Excess (\$) | 0.00 |
| | Assign From | GRACE TEO | Assign Date | 19/10/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | GOLDEN DRAGON (A) | c.c | 3759 |
| | Engine No. | HIDDEN | Year of Reg. | 2016 |
| | Chassis No. | LL3BDADE6GA002745 | Colour | WHITE |
| | Odometer | 226816 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | NIL |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 215/75 R17.5 | WEST LAKE | 6 mm |
| | L/H Front Tyre | 215/75 R17.5 | WEST LAKE | 6 mm |
| | R/H Rear Tyre | 215/75 R17.5 (D) | WEST LAKE | 3/3 mm |
| | L/H Rear Tyre | 215/75 R17.5 (D) | WEST LAKE | 3/3 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 18/10/2022 | Inspection Date | 20/10/2022 |
| | Survey held at | 566 WOODLANDS ROAD SINGAPORE 728697 | | |
| | Repairer | CONNECT3 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | |