Not Norhorias 1/Ling & Bearing After Pains Goldy,

CONNECTS

566 Woodlands Road (Mandai Estate) Singapore 728697 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

Roc: 53360061L GST: 53360061L

QT22/PC5479P/TPC

Sompo Insurance (Singapore) Pte Ltd	
50 Raffles Place #03-03	
Singapore Land Tower	
Singapore 048623	

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC5479P

No	. DESCRIPTION		QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Rear bumper	R	1	1,350.00	1,350.00
2.	Rear bumper LH bra	cket	1	380.00	380.00
3.	Rear LH taillamp	C	m 1	1,280.00	1,280.00
4.	Rear LH end panel or	1	A 2,650.00	2,650.00	
5.	Reverse sensor	1	Shan 300.00	300.00	
6.	Labour to remove & refit rear windscreen to assist repair		1	nn 350.00	350.00
7.		refit Lh chrome casing	1	100.00	100.00
3.	Sealant		4	nn 40.00	40.00
9.	Check wiring		1	30.00	30.00
0.	Labour to remove & refit rear seats & trims etc to assist repair		1	~~ 300.00	300.00
1.	Apply anti rust		1	n~ 50.00	50.00
2.	Labour charges		1	1,500.00	
3.	Spray painting		1	1,400.00	
1	100 MONTH TO THE TOTAL THE TOTAL TO THE TOTAL THE TOTAL TO THE TOTAL THE TOTAL TO T	LKK Auto Consultants her the Repairer of the followi • To resurvey before/after spray	ng:	SUB-TOTAL	8801-2354 NEW-2007 (1450)
•	Price before GST	To display damaged part(s) du			S\$9,730.00

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer