

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 30757

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0209/2020/NS  
Date : 26-Feb-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : **SGW 8889 X**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Kian Ngiap Sewing Machine Pte Ltd  
Address : 484, Geylang Road  
Singapore 389443  
Telephone : HP +65 98222200  
Type of Claim : OD Claim  
Policy No. : 2100456652-03  
Vehicle No : **SGW 8889 X**  
Model Code : Audi A4 AVANT 2.0T FSI MU  
Model / Year : Mar-16  
Engine No : CNC 148417  
Chassis No : WAUZZZ8KXFA186234  
Mileage : -  
Date In : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 25-Feb-20  
Place of Accident : Middle Road And Bencoolen Street Junction

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SGW 8889 X

| S/n                             | Nature of Jobs                                                                                                                                              |        | Estimated Charges  | Surveyor's Recommendations |
|---------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------------|----------------------------|
| 1                               | To remove and reinstall rear parking aid. Check function and renew according to damage.                                                                     | S/N \$ | 280.00             | x .                        |
| 2                               | To renew rhs 1/4 glass to facilitate fender renewal.                                                                                                        | S/N \$ | 300.00             | ✓ ✓                        |
| 3                               | To install 1/4 glass solar film.                                                                                                                            | S/N \$ | 200.00             | ✓ ✓                        |
| 4                               | To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.                              | S/N \$ | 1,400.00           | ✓ ✓                        |
| 5                               | To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc. | S/N \$ | 1,400.00           | ✓ ✓                        |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                                             | :      | <b>\$ 3,580.00</b> |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SGW 8889 X

| S/n                         | Nature of Jobs                                                                                                                                                                                                            |        | Estimated Charges   | Surveyor's Recommendations                                                                                                                  |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|---------------------|---------------------------------------------------------------------------------------------------------------------------------------------|
|                             |                                                                                                                                                                                                                           | c/f    |                     |                                                                                                                                             |
| 6                           | To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Inspect for damages.                                                                                                | S/N \$ | 560.00              | ✓ ✓                                                                                                                                         |
| 7                           | To dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy.                                                                                                                                         | S/N \$ | 300.00              | X.                                                                                                                                          |
| 8                           | To dismantle rear bumper, rear lid, rhs rear door and rhs front door. Cut out and weld rhs rear fender. To renew rhs rear door and rhs front door. Re-organise crash management components. Reinstall all parts removed.  | \$     | <del>7,000.00</del> | 4000. ✓                                                                                                                                     |
| 9                           | ✓ To respray rhs rear fender, rhs rear door, rhs front door, rhs wing mirror cover, door handle, rhs sill panel, door entrances, drain panel and end panelling. To carry out stone chip treatment and joint sealer works. | \$     | <del>6,350.00</del> | <div> <p>3025<br/><del>3125</del></p> <p>Fender + 2 door = 5.5<br/>5.5 x 550 = 3025?</p> <p>Mirror = <del>1000</del></p> <p>3125</p> </div> |
| 10                          | To reinstall sticker                                                                                                                                                                                                      | S/N \$ | 60.00               | ✓ ✓                                                                                                                                         |
| 11                          | To carry out diagnostic check.                                                                                                                                                                                            | S/N \$ | 192.00              | ✓ ✓                                                                                                                                         |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                           | :      | <b>\$ 18,042.00</b> |                                                                                                                                             |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SGW 8889 X

| S/N                           | Parts Description                            | Damaged Parts & Prices |           |
|-------------------------------|----------------------------------------------|------------------------|-----------|
|                               |                                              | S/Nett                 | Remarks   |
| 1                             | FRONT DOOR - RH <i>Dented</i>                | \$ 2,745.00            | ✓ 2196    |
| 2                             | FRONT DOOR OUTER SEAL <i>new</i>             | NEC \$ 193.00          | ✓ 154.40  |
| 3                             | BONDING AGENT <i>new</i>                     | NEC \$ 46.00           | ✓ 36.72   |
| 4                             | CLEANING SOLUTION <i>new</i>                 | NEC \$ 64.00           | ✓ 51.20   |
| 5                             | FRONT DOOR ATTACHMENT PARTS <i>new</i>       | \$ 84.00               | X         |
| 6                             | FRONT DOOR CATCH <i>new</i>                  | \$ 113.00              | ✓ 90.40   |
| 7                             | EXTERIOR MIRROR MOUNTING - RH <i>Damaged</i> | \$ 1,259.00            | ✓ 1007.20 |
| 8                             | MIRROR CAP - RH <i>cut</i> (By owner)        | \$ 538.00              | ✓ 400     |
| 9                             | TURN SIGNAL INDICATOR <i>cut</i>             | \$ 94.00               | ✓ 75.04   |
| 10                            | MIRROR GLASS - RH <i>shol new</i>            | \$ 1,563.00            | X.        |
| 11                            | FRONT WINDOW SLOT SEAL - RH <i>new</i>       | \$ 289.00              | X         |
| 12                            | TYRE PRESSURE DATA PLATE <i>new</i>          | \$ 18.00               | ✓ 14.40   |
| 13                            | REAR DOOR - RH <i>Distorted</i>              | \$ 2,745.00            | ✓ 2196    |
| 14                            | REAR DOOR ATTACHMENT PARTS <i>new</i>        | \$ 79.00               | X         |
| 15                            | REAR DOOR OUTER SEAL - RH <i>new</i>         | NEC \$ 209.00          | ✓ 167.20  |
| 16                            | BONDING AGENT <i>new</i>                     | NEC \$ 46.00           | ✓ 36.72   |
| 17                            | CLEANING SOLUTION <i>new</i>                 | NEC \$ 64.00           | ✓ X       |
| 18                            | REAR DOOR CATCH <i>new</i>                   | \$ 113.00              | ✓ 90.40   |
| 19                            | REAR WINDOW WELL TRIM STRIP - RH <i>new</i>  | \$ 279.00              | X         |
| 20                            | SIDE PANEL - RH <i>Punctured</i>             | \$ 2,549.00            | ✓ 2039.20 |
| SUB TOTAL SPARE PARTS CHARGES |                                              | : \$ 13,090.00         |           |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SGW 8889 X

| S/N                              | Parts Description                 | <u>Damaged Parts &amp; Prices</u> |          |
|----------------------------------|-----------------------------------|-----------------------------------|----------|
|                                  |                                   | S/Nett                            | Remarks  |
| 21                               | SIDE WINDOW - RH                  | \$ 444.00                         | ✓ 354.80 |
| 22                               | REAR SIDE WINDOW TRIM STRIPS - RH | \$ 307.00                         | ✓ 245.20 |
| 23                               | ACRYLIC SEALANT                   | S/N \$ 180.00                     | ✓ 180    |
| 24                               | CAVITY WAX                        | S/N \$ 140.00                     | ✓ 140    |
| 25                               | STONE CHIP                        | S/N \$ 180.00                     | ✓ 180    |
| 26                               | METAL FILLER POWDER               | S/N \$ 280.00                     | ✓ 280    |
| 27                               | 1/4 GLASS SEALANT                 | S/N \$ 100.00                     | ✓ 100    |
| 28                               | SUNDRIES                          | \$ 400.00                         | X 26.72  |
| <b>TOTAL SPARE PARTS CHARGES</b> |                                   | <b>: \$ 15,121.00</b>             |          |
| <b>TOTAL LABOUR CHARGES</b>      |                                   | <b>: \$ 18,042.00</b>             |          |
| <b>GRAND TOTAL</b>               |                                   | <b>: \$ 33,163.00</b>             |          |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : *Adrian*  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : *All Authorised, 14 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant