

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0902/2022/NK
DATE : 18-Oct-22
WIP : 46205

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/10/2022

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

OWNER'S NAME : MR CHENG WEE LEE
ADDRESS : 8 WHAMPAO EAST
#17-18
SINGAPORE 338520
TELEPHONE : HP +65 98786354
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100452170-06
VEHICLE NO : SCX 6810 C
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 23/2/2016
ENGINE NO : CVN 002216
CHASSIS NO : WAUZZZF47GA024373
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1410/2022
PLACE OF ACCIDENT : EUNOS POLYCLINIC CARPARK EXIT

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCX 6810 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	X n/a
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	/ ✓
3	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	280.00	X
4	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$	600.00	X
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	400.00	X
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	X
SUB LABOUR CHARGES		:	\$ 2,540.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCX 6810 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGES AND RENEW WHERE NECESSARY	S/N \$ 1,400.00	X
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN ATTACH, ETC	S/N \$ 1,400.00	X
9	TO DISMANTLE AND REINSTALL FRONT BUMPER AND REAR BUMPER. TO RENEW RHS FRONT DOOR AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER AND RHS SILL PANEL. TO REPAIR RHS B-PILLAR. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 9,500.00	2500 3000
10	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, DOOR HANDLES, RHS B-PILLAR, ROOF CHANNEL, RHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.	\$ 7,500.00	2950 ✓
11	TO RENEW RHS REAR RIM. TO CARRY OUT PRE/ POST WHEEL ALIGNMENT.	S/N \$ 520.00	X
12	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 23,052.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCX 6810 C

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	S/NETT	REMARKS
1	FRONT FENDER - RH <i>X Repi</i>	1	\$	861.00	688.80
2	FRONT FENDER ATTACHEMENTS PARTS <i>X</i>	1	\$	225.00	
3	FRONT FENDER CLOSING ELEMENT - RH <i>X</i>	1	\$	81.00	
4	FRONT FENDER BRACKET - RH <i>X</i>	1	\$	41.00	
5	FRONT FENDER BRACE - RH <i>X</i>	1	\$	132.00	
6	FRONT FENDER BRACKET FOR DEFORMATION ELEMENT - RH <i>X</i>	1	\$ <i>nn</i>	55.00	
7	FRONT FENDER BRACKET <i>X</i>	1	\$	36.00	
8	FRONT FENDER CLOSING ELEMENT - RH <i>X</i>	1	\$	37.00	
9	FRONT FENDER BRACKET <i>X</i>	1	\$	37.00	
10	FRONT WHEEL HOUSING LINER <i>X</i>	1	\$	262.00	
11	FRONT STONE CHIP GUARD <i>X MC</i>	1	\$	57.00	45.28
12	FRONT COVER <i>X</i>	1	\$	35.00	
13	FRONT COVER - RH <i>X</i>	1	\$	26.00	
14	FRONT DOOR <i>X Repi</i>	1	\$	3,431.00	
15	FRONT DOOR OUTER DOOR SEAL - RH <i>X</i>	1	\$	229.00	
16	BONDING AGENT 30 ML <i>X</i>	1	\$	51.00	
17	CLEANING SOLUTION 250 ML <i>X</i>	1	\$	74.00	
18	FRONT DOOR ATTACHMENTS PARTS <i>X</i>	1	TBC		
19	FRONT DOOR CATCH <i>X</i>	1	\$	116.00	
20	EXTERIOR MIRROR MOUNTING <i>X - Cut</i>	1	\$	991.00	792.40
SUB TOTAL SPARE PARTS			:	\$ 6,777.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCX 6810 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	MIRROR CAP - RH <i>X NN</i>	1	\$ 308.00	
22	MIRROR GLASS - RH <i>/ Cat</i>	1	\$ 1,757.00	1405.60
23	FRONT TRIM PLATE FOR DOOR HANDLE <i>X { NN</i>	1	\$ 98.00	
24	DATA PLATE FOR TYRE PRESSURE <i>X</i>	1	\$ 42.00	
25	REAR DOOR - RH <i>/ Bnc</i>	1	\$ 3,431.00	2744.80
26	REAR DOOR OUTER SEAL - RH <i>/</i>	1	\$ 229.00	182.80
27	BONDING AGENT <i>/</i>	1	\$ 51.00	40.56
28	CLEANING SOLUTION 250 ML <i>/</i>	1	\$ 74.00	58.96
29	APPLICATOR FRONT / REAR DOOR <i>/</i>	1	\$ 18.00	
30	SEALING STRIPS <i>X</i>	1	\$ 19.00	
31	REAR DOOR ATTACHMENTS PARTS <i>X</i>	1	\$ 943.00	
32	REAR DOOR CATCH <i>X</i>	1	\$ 134.00	
33	REAR DOOR TRIM PLATE FOR DOOR HANDLE - RH <i>X</i>	1	\$ 98.00	
34	REAR DOOR HANDLE HOUSING <i>X</i>	1	\$ 9.00	
35	REAR DOOR COVER - RH <i>X</i>	1	\$ 7.00	
36	MOUNTING BAR - RH <i>X</i>	1	\$ 183.00	
37	REAR DOOR WINDOW REGULATOR <i>X</i>	1	\$ 305.00	
38	SIDE PANEL FRAME - RH <i>X Rym</i>	1	\$ 3,199.00	
39	RIVETTED CAP NUT <i>/ { MCL</i>	2	\$ 7.00	5.60
40	CLIPS <i>/</i>	10	\$ 9.00	7.20
SUB TOTAL SPARE PARTS		:	\$ 10,921.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL NDRA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCX 6810 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	WHEEL HOUSING LINERS - RH X	1	S	260.00	
42	REAR WINDSCREEN X	1	S	1,287.00	
43	REAR 1/4 GLASS X	1	S	685.00	
44	PRIMER X	2	S	44.00	
45	HINGE HALVES LOWER RH X	2	S	106.00	
46	ACRYLIC SEALANT X	S/N	S	180.00	
47	CAVITY WAX X	S/N	S	140.00	
48	STONE CHIP  	S/N	S	180.00	180
49	METAL FILLER POWDER X	S/N	S	280.00	
50	1/4 GLASS SEALANT X	S/N	S	100.00	
51	REAR WINDSCREEN SEALANT X	S/N	S	200.00	
52	RHS REAR RIM X			TBC	
53	SUNDRIES ?	S		600.00	134.08
TOTAL SPARE PARTS		:	\$	21,760.00	
TOTAL LABOUR CHARGES		:	\$	23,052.00	
GRAND TOTAL		:	\$	44,812.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME	:	Amo Arg
SURVEYED DATE	:	
AUTHORISED DATE	:	2 Days
EXCESS COST	:	
LIABILITY	:	before first photo
REMARKS	:	19/10

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after repair painting
- To disassemble & reassemble the survey
- Repair & reassemble
- To repair & reassemble on a part basis
- To repair & reassemble on a full body
- To repair & reassemble on a full body

Is this repairer a member of the LKK company

Acknowledged by: _____ for _____

Signature: _____

Date: _____