

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0906/2022/EQ
DATE : 19-Oct-22
WIP : 46559

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR PANG KEM CHOW
ADDRESS : 138 THOMSON RIDGE
SINGAPORE 574720

TELEPHONE : HP +65 83837109
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210135141
VEHICLE NO : **SNC 7953 Y**
MODEL CODE : AUDI E-TRON ADVANCED 50 Q
MODEL YEAR : 16/11/2021
ENGINE NO : EAS 081828
CHASSIS NO : WAUZZZGEXNB003452
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Oct-22
PLACE OF ACCIDENT : MBS CARPARK B4

55 UBI ROAD 1, SINGAPORE 408699


TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC 7953 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	/
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00	/
3	TO REMOVE AND RENEW AIRCON CONDENSER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,800.00	?
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	?
5	TO DEACTIVATE AND RE-ACTIVATE HIGH VOLATAGE SYSTEM FOR VEHICLE.	S/N \$ 480.00	/
TOTAL LABOUR CHARGES		: \$ 4,410.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC 7953 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S 6,300.00	1200
7	TO RESPRAY FRONT BUMPER, LHS FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS. <i>500</i> <i>250</i> <i>Front Rear LH</i>	S 4,500.00	2550 + 600 ✓
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N S 192.00	✓
TOTAL LABOUR CHARGES		: S 15,402.00	

Stn (LKF)

11/11/22

PREMIUM AUTOMOBILES

UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 7953 Y

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER / BR	1	S	2,896.00
2	FRONT BUMPER TRIM - LH / RH	2	S	130.00
3	FRONT BUMPER FIXING PARTS	1	S	658.00
4	FRONT BUMPER CLOSING ELEMENT - CENTER	1	S / BR	248.00
5	FRONT BUMPER FOAM PART - LH	1	S / BR	34.00
6	FRONT BUMPER COVER - LH / RH	2	S	78.00
7	FRONT BUMPER FOAM PART - UPPER	1	S / BR	150.00
8	FRONT BUMPER FOAM PART - LOWER	1	S	125.00
9	FRONT BUMPER PLASTIC FOAM STRIP	1	S	134.00
10	FRONT BUMPER GRILLE - LOWER CENTRE	1	S	283.00
11	FRONT BUMPER GRILLE - CENTER	1	S / BR	171.00
12	FRONT BUMPER CLOSING ELEMENT - LOWER	1	S	235.00
13	FRONT BUMPER AIR GUIDE - LH	1	S	101.00
14	FRONT BUMPER IMPACT PROTECTION	1	S	899.00
15	FRONT BUMPER SPOILER - LH	1	S	175.00
16	RADIATOR AIR GUIDE - LH OUTER	1	S	58.00
17	RADIATOR AIR GUIDE - LH INNER	1	S	45.00
18	RADIATOR AIR GUIDE - LH	1	S	134.00
19	RADIATOR GRILLE	1	S	2,317.00
20	RADIATOR GRILLE COVER CAP	1	S	141.00
SUB TOTAL SPARE PARTS		:	\$	9,012.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




SUBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 7953 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	RADIATOR GRILLE COVER	1	S	69.00
22	RADIATOR GRILLE CLOSING ELEMENT	1	S - BR	246.00
23	RADIATOR GRILLE COVER - LH / RH	2	S	122.00
24	FRONT CAMERA	1	S	1,006.00
25	FRONT BUMPER REINFORCEMENT BEAM	1	S	1,451.00
26	FRONT BUMPER CROSS MEMBER	1	S	464.00
27	RADIATOR SUPPORT BRACKET	1	S	481.00
28	RADIATOR SIGHT SHIELD - LOWER	1	S	118.00
29	RADIATOR SIGHT SHIELD - UPPER	1	S - top cover	119.00
30	RADIATOR GUIDE SECTION - LH	1	S	50.00
31	RADIATOR BRACKET - LH	1	S	87.00
32	WARNING SIGN LABEL	1	S	21.00
33	HORN HIGH TONE - LH	1	S	162.00
34	HORN BRACKET - LH	1	S	25.00
35	FRONT PARKING AID SENSOR - (INNER) / OUTER	1	S	584.00
36	FRONT PARKING AID SEAL RING	4	S	10.00
37	FRONT PARKING AID SENSOR	1	S	292.00
38	FRONT BUMPER WIRING SET	1	S	642.00
39	FRONT FENDER - LH	1	S	2,477.00
40	HEADLIGHT SEAL - LH	1	S	60.00
SUB TOTAL SPARE PARTS			S	8,486.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




5 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 7953 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER BRACKET - LH ?	1	S	11.00
42	FRONT FENDER BRACKET - LH CENTRE ?	1	S	15.00
43	FRONT FENDER BRACKET - LH REAR ?	1	S	15.00
44	FRONT FENDER MOUNT BRACKET - LH ? - BT	1	S	76.00
45	FRONT FENDER BRACKET - LH INNER ?	1	S	18.00
46	BONNET / BT	1	S	5,482.00
47	BONNET IMPACT PROTECTION - LH / CENTER / RH ✓	3	S	134.00
48	BONNET STRIKER - LH X	1	S	134.00
49	BONNET RELEASE ELEMENT X	1	S	65.00
50	BONNET LOCK X	1	S	228.00
51	BONNET BOWDEN CABLE - CENTER X	1	S	64.00
52	BONNET BOWDEN CABLE COVER X	1	S	11.00
53	BONNET RELEASE LEVER X	1	S	16.00
54	BONNET LOCK CABLE X	1	S	82.00
55	HEADLIGHT - LH / CA	1	S	8,660.00
56	LIFT CYLINDER - LH X	1	S	259.00
57	LIFT CYLINDER HOSE X - In	1	S	111.00
58	LOCK CARRIER ?	1	S	1,283.00
59	READY-MIX COOLANT ?	6	S	297.00
60	RADIATOR AIR GUIDE - LH / RH ?	2	S	58.00
SUB TOTAL SPARE PARTS		:	\$	17,019.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



SUBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 7953 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	RADIATOR AIR GUIDE - UPPER / LOWER ? <i>AK</i>	2 S		76.00	
62	RADIATOR AIR GUIDE - REAR LOWER / UPPER ? <i>AK</i> <i>21</i>	1 S		127.00 88.00	
63	AIR CONDITIONER STICKER ? <i>AK</i>	1 S		21.00	
64	FRONT WHEEL COVER - LH / RH <i>AK</i>	2 S		1,086.00	
65	FRONT NO PLATE <i>AK</i>	S/N S		60.00	
66	SUNDRIES ?	S		500.00	
TOTAL SPARE PARTS		:	\$	36,437.00	
TOTAL LABOUR CHARGES		:	\$	15,402.00	
GRAND TOTAL		:	\$	51,839.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.




Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0906/2022/EQ 11-Nov-22 CHANG 1 of 1 SNC 7953 Y AUDI E-TRON ADVANCED 50 QU
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	TOP COVER CLIP <i>rec</i>	\$ 77.00	
	GRAND TOTAL	\$ 77.00	

For Premium Automobiles Pte Ltd

Steve (LKK)
11/11/22



Authorized Signature



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

6 Days.
Refuse paint repair
Car Acc
Not Authorised!

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

19/10.

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display new body parts during resurvey
- Parts at the repairer's discretion
- The repairer is to be on a "no recourse" basis
- Repairer is to be on a "no recourse" basis
- Supplier is to be on a "no recourse" basis and is subject to the insurance company's decision

Acknowledged by Repairer
Signature:
Date: