

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC22P00101800	Date of Loss:	16/09/2022
Vehicle Reg. No.:	SMQ8563X	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HOGBERG FRED RICKAD ROBIN WILLIAM		
Make/Model:	BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A)	Vehicle Reg. Date:	12/11/2014
Vehicle Colour:	White	Chassis No:	WBA5A32040D335236
Engine No:	A5900678N20B20B		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	6,483.40
Miscellaneous Items	35.00
Labour	1,100.00
Paintwork Labour	600.00
Towing	0.00
Gross Total (\$\$)	8,218.40
+ GST 7.00% (\$\$)	575.29
Nett Amount (\$\$)	8,793.69

This claim is handled by: LAI YEAN KUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Oct 2022)
 Parts: 143 BMW 520I 2.0 AT D/AB 2WD 4DR LED NAV (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Accord Auto Services Pte Ltd/SMQ8563X/19/10/2022 19:03
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>BR</i>	0.00	0.00	*1,680.00 F ✓
2	1		*FRONT LH BUMPER SIDE RETAINER <i>1</i> X NN	0.00	0.00	*65.00 F
			*RH			
3	1		*FRONT BUMPER TOW COVER X NN	0.00	0.00	*80.00 F
4	1		*FRONT RH NUZZLE COVER <i>1</i> X NN	0.00	0.00	*85.00 F
5	1		*FRONT RH FENDER X R	0.00	0.00	*720.00 F
6	8		*FRONT FENDER SHIELD RIVET X NN	0.00	0.00	*24.00 F
7	1		*FRONT BUMPER SENSOR SEAL SET <i>1</i> X NN	0.00	0.00	*40.00 F X
8	1		*FRONT RH HEADLAMP <i>BR</i>	0.00	0.00	*3,200.00 F ✓

F=Franchise part.

Sub Total (S\$) 5,894.00
 + Margin on L,N Items 10.00% (S\$) 589.40
 Total Parts (S\$) 6,483.40

Accord Auto Services Pte Ltd/SMQ8563X/19/10/2022 19:03. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

fy by car - my

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
		<u>Miscellaneous Items</u>	35.00 ✓
1	1	FRONT BUMPER CLIPS	
		Sub Total (\$)	35.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
	<u>Paintwork Labour</u>		
1	Spray Painting to All Affected Areas	New 251	600.00
	<u>Labour Items</u>		
2	Labour Remove / Refix Accident Damages Parts To Knock , Jack, Cut Weld and Realign	New 600	800.00
	Accident Affected Area	New 152	300.00
3	Computer Diagnostic(Reset Necessary Electronic Function)		
	Gross Labour Cost (\$)		1,700.00

Accord Auto Services Pte Ltd/SMQ8563X/19/10/2022 19:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)
26/10/22, 4.37p
OD- M AL
EXCISE ?
PIP
My BL y
4 djs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: