

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 27 Oct 2022

Preliminary Advice

Vehicle No	: SMQ8563X	Accident Date	: 16/09/2022
Make	: BMW 520I	Policy No.	: MPC22P00101800
Assignment Date	: 20/10/2022	Excess	: S\$0.00
Date of Inspection	: 26/10/2022	Est. Duration of Repair	: 04 DAYS
Inspection At	: ACCORD AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,218.40
Revised Amount	:S\$	6,447.00
Check Items (Estimated)	:S\$	165.00
Total	:S\$	6,612.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	63,000.00
COE / PARF Rebate	:S\$	43,418.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,582.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Part by Part repair.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.