

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Melody Teoh

Date: 01 Feb 2023

**Preliminary Advice**

Vehicle No	: YP5324C	Accident Date	: 08/10/2022
Make	: HINO XZU710R-HKFMS3	Policy No.	: DMFG22001147
Assignment Date	: 20/10/2022	Excess	: S\$1,000.00
Date of Inspection	: 20/10/2023	Est. Duration of Repair	: 16 DAYS
Inspection At	: CHENG HOE MOTOR PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,488.30	(EST \$35,488.70 + SUPP \$3,999.60)
Revised Amount	:S\$	18,175.50	(REV \$1,4175.90 + SUPP \$3,999.60)
Check Items (Estimated)	:S\$	20,201.80	
Total	:S\$	38,377.30	
Lump Sum Repair	:S\$		

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	63,000.00
COE / PARF Rebate	:S\$	21,681.00
Salvage Value	:S\$	
Margin for Repair	:S\$	41,319.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Kindly approve on Supplementary items.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.