

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 5448R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID (CONSISTENT)	TO REPAIR SEE LABOUR	1,732.50	-
1	BOOTLID LOGO 'BMW' (CONSISTENT)	NECESSARY	78.00	78.00
1	BOOTLID LOCK (CONSISTENT)	NOT NECESSARY	532.10	-
1	REAR BUMPER M5 SPORT (CONSISTENT)	DISTORTED / MTG BROKEN	2,653.00	2,255.05
1	REAR BUMPER LOWER LID (CONSISTENT)	NOT NECESSARY	1,056.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	835.20	679.80
1	REAR BUMPER CENTRE RETAINER (CONSISTENT)	BROKEN	265.00	182.30
2	REAR BUMPER SIDE BRACKETS LH/RH @\$210.50 (CONSISTENT)	BROKEN	421.00	281.50
1	REAR EXHAUST SYSTEM (CONSISTENT)	TO REPAIR SEE LABOUR	4,651.00	-
	LESS 5% DISCOUNT		-611.19	-
	LESS 10% DISCOUNT		-	-347.67
			11,612.61	3,128.98
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	60.00	30.00
2	REAR BUMPER SENSOR @\$321.00 (SN) (CONSISTENT)	DAMAGED	642.00	370.00
			702.00	400.00
	<u>LABOUR</u>			
	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR EXHAUST SYSTEM .		1,200.00	500.00
	SPRAY PAINTING ON ACCIDENT AREAS .		800.00	600.00
	WIRING CHARGE.		100.00	30.00
	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS .	NOT NECESSARY	100.00	-
			2,200.00	1,130.00
	GRAND TOTAL		14,514.61	4,658.98

Report Ref No. CC4/ASM22010418/Dpa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,700.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CC4/ASM22010418/Dpa3q2



**Automotive Assessor / Investigator**