



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA			Ref: CC4/ASM22010418/Dpa3q2 Date: 16/01/2023 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 2022Z	Veh. Inspected	SMQ 5448R
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M04D58	Excess (\$)	0.00
	Assign From		Assign Date	19/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 523I	c.c	2497
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	WBAFP32000C257871	Colour	GREEN
	Odometer	232249 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R20	MICHELIN	5 mm
	L/H Front Tyre	245/40 R20	MICHELIN	5 mm
	R/H Rear Tyre	275/35 R20	MICHELIN	5 mm
	L/H Rear Tyre	275/35 R20	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/10/2022	Inspection Date	25/10/2022
	Survey held at	A T AUTO CONSULTANT 113 TECK WHYE LANE, #05-650, SINGAPORE 680113		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	