

ASS. REC. BY:

REF:

CC4/ASM22010418/Dp2

ASSIGNMENT

C012 March 2030

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repair: _____

4

days

Res: _____

Yes or No

Lum Sum: _____

20

%

3 Val: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMQ 5448R Yr Regn: April 2010

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 523i c/c 2497Colour: Green A/C: Insured / Std / NI / NASp. Reading: 232249 T/Radio: Insured / Std / NI / NAEng No: 02087383H52B25AFC/No: WBAFP32000C257871

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: 245/40 R 20R: 275/35 R 20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Michelin

Front

Rear

R/Bal: 5 mmR/Bal: 5 mmL/Bal: 5 mmL/Bal: 5 mmD.O.A. 17/10/2022D.O.I. 25/10/2022

Survey held at

AI Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

AXA SHIA 2022 ZMV 851CLTA 26.3KHL 58.7K14/11/22 figure 2/5 3,700/- with 4 days delay

Date/Time, File Pass to?

☐ : Prel. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Format: _____

Lump Sum / I.B.J. (\$) _____

Days of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

Site Insp. (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

\$ - \$ - \$

Photos

Others

TOTAL

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 18.10.2022
Vehicle No: SMQ5448R
Owner: NUR ALIYAH BTE KHAMIS
Date of Accident: 17.10.2022
Make & Model: BMW 523I
Chassis No : WBAFP32000C257871

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE FOR ACCIDENT VEHICLE NOS SMQ5448R

PARTS

1	1 Bootlid		\$1,732.50	X
2	1 Bootlid logo "BMW"		\$78.00	✓
3	1 Bootlid lock		\$532.10	X
4	1 Rear bumper M5 sport	distorted / mostly broken	\$2,653.00	✓ 2255.05
5	1 Rear bumper lower lid		\$1,056.00	X
6	1 Rear bumper reinforcement		674.80 \$835.20	✓
7	1 Rear bumper centre retainer	broken	182.30 \$265.00	✓
8	2 Rear bumper side brackets RH/LH	broken	@ 140.75 \$281.50	✓ 281.50
9	1 Rear exhaust system		\$4,651.00	X
SUB TOTAL			\$12,223.80	
LESS 5% 10%			\$611.19	
DISCOUNTED SUB TOTAL			\$11,612.61	

S. NETT ITEM

1	1set Rear bumper clips		\$60.00	30/-
2	2 Rear bumper sensor		\$321.00	642.00
SUB TOTAL			\$702.00	
LESS 0 %			\$0.00	
DISCOUNTED SUB TOTAL			\$702.00	

LABOUR

1	Panel beating for replace and repair affected parts		\$1,200.00	500/-
2	Spray painting on accident areas		\$800.00	600/-
3	Wiring charges		\$100.00	30/-
5	Apply undercoating to above affected areas		\$100.00	44
SUB TOTAL (LABOUR)			\$2,200.00	

SUB TOTAL (PARTS)	\$11,612.61
SUB TOTAL (S.NETT)	\$702.00
SUB TOTAL (LABOUR)	\$2,200.00
ESTIMATED GRAND TOTAL	\$14,514.61

25/10/2022 @ 1300hrs

N/A Andri

2/sum 4

3 days

2KK Auto

Check part prices.

4658.98

1/5 3,710.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 485Z

Vehicle Details

Vehicle No.: SMQ5448R

Vehicle to be Exported: Yes

Intended Deregistration Date: 24 Oct 2022

Vehicle Make: B.M.W.

Vehicle Model: 523i 2.5 AT ABS D/AB 2WD 4DR GAS/D

Primary Colour: Black

Manufacturing Year: 2010

Engine No.: 02087383N52B25AF

Chassis No.: WBAFP32000C257871

Maximum Power Output: 150.0 kW (201 bhp)

Open Market Value: \$40,475.00

Original Registration Date: 30 Apr 2010

First Registration Date: 30 Apr 2010

Transfer Count: 6

Actual ARF Paid: \$40,475.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Mar 2030

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

PQP Paid: \$35,416.00

COE Rebate Amount: \$26,333.00

Total Rebate Amount: \$26,333.00

The information contained herein is correct as at 24 Oct 2022

OK