

ASS. REC. BY:

REF:

CC4/ASM22010418/Dp2

ASSIGNMENT

C02 March 2020

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh. had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

4

days

Res: _____

Yes or No

Lum Sum: _____

20

%

3 Val: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SMQ 5448R

Yr Regn: _____

April 2010

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

BMW 523i

c/c

2497

Colour: _____

Green

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

232249

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

02087383H52B25AF

C/No: _____

WBAFP32000C257871

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rrim or

Tyre Size: _____

F: _____

245 / 40 R 20

R: _____

275 / 35 R 20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / RIR / SUMI /

TOYO / YOKO or

Michelin

Front

Rear

R/Bal: _____

S

mm

R/Bal: _____

S

mm

L/Bal: _____

S

mm

L/Bal: _____

S

mm

D.O.A. _____

17/10/2022

D.O.I. _____

25/10/2022

Survey held at

AI Auto

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	AXA SHA 2022 Z
	MV 851C
	LTA 26.3K
	HL 58.7K
14/11/22	Phone 215 3,7001 - with 4 days of rep

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days of Repair: _____

Resurvey No. of Trips: _____

Survey Fee: _____

Transportation: _____

S + PS St

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)

Add Fee: _____



Site Insp. (\$ _____)



Interview (\$ _____)



Tech. Invs (\$ _____)



Weekend (\$ _____)

AT AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Date of Estimate: 18.10.2022
Vehicle No: SMQ5448R
Owner: NUR ALIYAH BTE KHAMIS
Date of Accident: 17.10.2022
Make & Model: BMW 523i
Chassis No : WBAFP32000C257871

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE FOR ACCIDENT VEHICLE NOS SMQ5448R

PARTS

1	1 Bootlid		\$1,732.50	X
2	1 Bootlid logo "BMW"		\$78.00	✓
3	1 Bootlid lock		\$532.10	X
4	1 Rear bumper M5 sport	distorted / mostly broken	\$2,653.00	✓ 2255.05
5	1 Rear bumper lower lid		\$1,056.00	X
6	1 Rear bumper reinforcement	broken	679.80 \$835.20	✓
7	1 Rear bumper centre retainer	broken	182.30 \$265.00	✓
8	2 Rear bumper side brackets RH/LH	broken	@ 140.75 \$281.50	✓ 281.50
9	1 Rear exhaust system		\$4,651.00	X
SUB TOTAL			\$12,223.80	
LESS 5% 10%			\$611.19	
DISCOUNTED SUB TOTAL			\$11,612.61	

S. NETT ITEM

1	1set Rear bumper clips		\$60.00	30/-
2	2 Rear bumper sensor		\$321.00	372.00
SUB TOTAL			\$702.00	
LESS 0 %			\$0.00	
DISCOUNTED SUB TOTAL			\$702.00	

LABOUR

1	Panel beating for replace and repair affected parts		\$1,200.00	500/-
2	Spray painting on accident areas		\$800.00	600/-
3	Wiring charges		\$100.00	30/-
5	Apply undercoating to above affected areas		\$100.00	44
SUB TOTAL (LABOUR)			\$2,200.00	

25/10/2022 @ 1300m

N/A Andu

2/sum

4

8 days.

Tyzen

2KK Auto

Check part prices.

4658.98

4/5 3,710.00