

Date : 20/10/2022  
Vehicle No: SME8882M  
Model: FERRARI F8 TRIBUTO S-A  
Chassis: ZFF92LMC000262643-2021  
Reg.Year: 2022  
Policy No: DMPPHQ22-005606  
Date of Accident: 07/10/2022  
Estimator: TING AN

TO MOTOR CLAIM DEPT  
EQ INSURANCE  
5 Maxwell Road, #17-00 Tower Block  
MND Complex  
Singapore 069110

*NOT Authorised  
Pursuing By claim  
Ex @ 15,000/-*

*28 days*

**ESTIMATE**

| NO. | DESCRIPTION                                  | QTY | UNIT S\$   | AMOUNT S\$  |
|-----|----------------------------------------------|-----|------------|-------------|
| 1   | FRONT DOOR LH                                | 1   | By         | \$30,000.00 |
| 2   | FRONT DOOR OUTER HANDLE LH                   | 1   | By         | \$1,900.00  |
| 3   | FRONT DOOR OUTER HANDLE SEAL LH              | 1   | By         | \$180.00    |
| 4   | FRONT DOOR LOCK LH                           | 1   | CM         | \$750.00    |
| 5   | FRONT DOOR LOWER WEATHERSTRIP LH             | 1   | By         | \$1,900.00  |
| 6   | FRONT DOOR UPPER WEATHERSTRIP LH <i>midy</i> | 1   | By         | \$1,650.00  |
| 7   | FRONT DOOR REGULATOR LH                      | 1   | Dist/By    | \$2,400.00  |
| 8   | FRONT DOOR INNER BRACKET LH                  | 1   | CM         | \$1,000.00  |
| 9   | REAR FENDER LH                               | 1   | By         | \$65,000.00 |
| 10  | REAR FENDER QUARTER GLASS LH                 | 1   | midy By    | \$2,400.00  |
| 11  | REAR FENDER INNER SHIELD (FRONT)             | 1   | Refurn/Dri | \$3,800.00  |
| 12  | REAR FENDER INNER SHIELD (REAR)              | 1   | Dist/CM    | \$1,600.00  |
| 13  | SIDE SKIRT CARBON FIBER LH                   | 1   | CM         | \$36,500.00 |
| 14  | SIDE SKIRT KICK PLATE LH                     | 1   | By         | \$1,200.00  |
| 15  | SIDE SKIRT RETAINER LH                       | 1   | By         | \$140.00    |
| 16  | REAR AIR INTAKE LH                           | 1   | CM         | \$2,100.00  |
| 17  | REAR AIR INTAKE GASKET SHIELD LH             | 1   | By         | \$400.00    |
| 18  | REAR AIR INTAKE UPPER & LOWER FOAM           | 1   | By         | \$250.00    |
| 19  | REAR AIR INTAKE SIDE FOAM                    | 1   | By         | \$330.00    |
| 20  | ENGINE COMPARTMENT COVER CARBON FIBER LH     | 1   | CM         | \$12,000.00 |
| 21  | ENGINE COMPARTMENT LID GRILLE LH             | 1   | Ref/Dri    | \$1,800.00  |
| 22  | ENGINE UNDER COVER                           | 1   | CM         | \$2,600.00  |
| 23  | ENGINE UNDER COVER BRACKET                   | 1   | By         | \$850.00    |
| 24  | REAR RIM LH                                  | 1   | By         | \$17,000.00 |
| 25  | REAR UPPER ARM LH                            | 1   |            | \$2,600.00  |
| 26  | REAR LOWER ARM LH                            | 1   |            | \$4,200.00  |
| 27  | REAR KNUCKLE ARM LH                          | 1   |            | \$8,500.00  |
| 28  | REAR STABILIZER BAR LINK LH                  | 1   |            | \$900.00    |
| 29  | REAR TIE ROD LH                              | 1   |            | \$1,400.00  |
| 30  | REAR BUMPER                                  | 1   | CM         | \$39,900.00 |
| 31  | REAR BUMPER LOWER DIFFUSER CARBON FIBER      | 1   | CM         | \$38,400.00 |
| 32  | REAR SPOILER                                 | 1   | CM         | \$29,000.00 |
| 33  | REAR SPOILER THIRD BRAKE LIGHT               | 1   | By         | \$900.00    |

**Head office**

8 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1003

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6401 1622 | Fax: (+65) 6401 1011



**OPTIMA WERKZ**  
SINGAPORE

OPTIMA WERKZ PTE LTD

Co. Reg. No. 201212455W

www.ow.sg

/OptimaWerkz

@ /OptimaWerkz

Date : 20/10/2022  
Vehicle No: SME8882M  
Model: FERRARI F8 TRIBUTO S-A  
Chassis: ZFF92LMC000262643-2021  
Reg. Year: 2022  
Policy No: DMPPHQ22-005606  
Date of Accident: 07/10/2022

TO MOTOR CLAIM DEPT

EQ INSURANCE

5 Maxwell Road, #17-00 Tower Block

MND Complex

Singapore 069110

|    |                                       |   |          |                |              |
|----|---------------------------------------|---|----------|----------------|--------------|
| 34 | REAR SPOILER BRACKET                  | 1 |          | Bu \$1,680.00  | ✓            |
| 35 | REAR BUMPER REINFORCEMENT             | 1 |          | Bu \$5,700.00  | ✓            |
| 36 | REAR BUMPER UPPER BRACKET LH          | 1 |          | Diy \$160.00   | ✓            |
| 37 | REAR BUMPER WIRING HARNESS            | 1 |          | W/D \$4,200.00 | ✓            |
| 38 | REAR BUMPER PARKING SENSOR WIRING     | 1 |          | T \$900.00     | ✓            |
| 39 | REAR BUMPER REFLECTOR LH              | 1 |          | B \$250.00     | X            |
| 40 | REAR BUMPER REFLECTOR BASE BRACKET LH | 1 |          | CM \$200.00    | ✓            |
| 41 | REAR BUMPER PARKING SENSOR            | 1 |          | B \$350.00     | ✓            |
| 42 | REAR BUMPER PARKING SENSOR O-RING     | 1 |          | B \$50.00      | ✓            |
| 43 | REAR BUMPER "FERRARI" EMBLEM          | 1 |          | B \$750.00     | ✓            |
| 44 | REAR EXHAUST TIP LH                   | 1 |          | B \$220.00     | X            |
| 45 | REAR EXHAUST MUFFLER LH               | 1 |          | B \$4,500.00   | X            |
| 46 | REAR EXHAUST BRACKET LH               | 1 |          | B \$185.00     | X            |
| 47 | REAR EXHAUST MOUNTING                 | 2 | \$165.00 | B \$330.00     | X            |
| 48 | REAR TAIL LAMP LH (OUTER)             | 1 |          | B \$3,000.00   | ✓            |
| 49 | REAR TAIL LAMP LH (INNER)             | 1 |          | W/D \$3,280.00 | ✓            |
| 50 | REAR TAIL LAMP BASE BRACKET LH        | 1 |          | CM \$380.00    | ✓            |
| 51 | REAR FENDER RH                        | 1 |          | REPAIR         | ✓            |
|    |                                       |   |          | SUB TOTAL      | \$339,685.00 |
|    |                                       |   |          | LESS 10%       | \$33,968.50  |
|    |                                       |   |          | PARTS TOTAL    | \$305,716.50 |

| NO. | SPECIAL NETT                         | QTY | UNIT S\$ | AMOUNT S\$ |            |
|-----|--------------------------------------|-----|----------|------------|------------|
| 1   | FRONT DOOR INNER TRIM BOARD CLIPS LH | 1   |          | B \$150.00 | ✓          |
| 2   | SIDE SKIRT SCREW & CLIPS             | 1   |          | B \$150.00 | ✓          |
| 3   | REAR FENDER QUARTER GLASS SEALANT    | 1   |          | B \$120.00 | ✓          |
| 4   | REAR FENDER INNER SHIELD CLIPS LH    | 1   |          | B \$120.00 | ✓          |
| 5   | ENGINE COMPARTMENT GRILLE CLIPS      | 1   |          | B \$100.00 | ✓          |
| 6   | ENGINE UNDER COVER CLIPS             | 1   |          | B \$120.00 | ✓          |
| 7   | REAR BUMPER SCREW                    | 1   |          | B \$150.00 | ✓          |
| 8   | REAR BUMPER LOWR DIFFUSER SCREW      | 1   |          | B \$150.00 | ✓          |
|     |                                      |     |          | S/N TOTAL  | \$1,060.00 |

Head office

6 Kung Chong Road Singapore 150143

Tel (+65) 6472 1313 | Fax (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel (+65) 6484 0910 | Fax (+65) 6481 1003

Branch (Motor Insurance Claims)

811 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047

Tel (+65) 6481 1522 | Fax (+65) 6481 1011





Aspire 3

DDR4

Faster  
memory  
speed

• Intel® Celeron®

• Intel® UHD Graph

• 4 GB DDR4 Memo

**OPTIMA WERKZ**  
SINGAPORE

OPTIMA WERKZ PTE LTD

Co. Reg. No. 201212455W

www.ow.sg

/OptimaWerkz

© OptimaWerkz

Date : 20/10/2022  
 Vehicle No: SME8882M  
 Model: FERRARI F8 TRIBUTO S-A  
 Chassis: ZFF92LMC000262643-2021  
 Reg.Year: 2022  
 Policy No: DMPPHQ22-005606  
 Date of Accident: 07/10/2022

**TO MOTOR CLAIM DEPT****EQ INSURANCE**

5 Maxwell Road, #17-00 Tower Block  
 MND Complex  
 Singapore 069110

**LABOUR CHARGES:**

|                                                                                                                                                            |            |      |
|------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------|
| LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST ACCIDENT AREAS & ETC.                                                                                  | \$3,000.00 | 2400 |
| LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH, ROCKER PANEL LH, REAR FENDER LH, REAR FENDER RH, REAR BUMPER & ETC. | \$2,500.00 | 2000 |
| LABOUR CHARGES TO DISCONNECT, REMOVE & REFIX FRONT DOOR INNER WIRING HARNESS & ETC. TO EFFECT REPLACE OF FRONT DOOR LH.                                    | \$300.00   | 150  |
| LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR LH.                                               | \$300.00   | 150  |
| LABOUR CHARGES TO REMOVE & REFIX INNER TRIM & UPHOLDSTERY SET & ETC. TO EFFECT REPLACE OF REAR FENDER LH.                                                  | \$500.00   | 350  |
| LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS LH & ETC.                                                                                              | \$200.00   | 80   |
| LABOUR CHARGES TO REMOVE & REPLACE REAR PARKING SENSOR & ETC.                                                                                              | \$200.00   | 100  |
| LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER WIRING HARNESS & ETC. TO EFFECT REPLACE OF REAR BUMPER, BUMPER LOWER DIFFUSER.                              | \$250.00   | 200  |
| LABOUR CHARGES TO REMOVE & REPLACE REAR EXHAUST MUFFLER, REAR EXHAUST MOUNTING, REAR EXHAUST BRACKET & ETC.                                                | \$350.00   | X    |
| TO MOUNT VEHICLE ONTO CAR-O-LINER TO CALIBRATE SUB CHASSIS FRAME & BODY BACK TO MANUFACTURING SPECIFICATIONS.                                              | \$800.00   | X    |
| LABOUR CHARGES TO REMOVE & REPLACE REAR UPPER ARM LH, REAR LOWER ARM LH, REAR KNUCKLE ARM LH, REAR TIE ROD, REAR STABILIZER BAR LINK & ETC.                | \$500.00   | 300  |
| TO WHEEL ALIGNMENT & BALANCING.                                                                                                                            | \$150.00   | 120  |

**Head office**

6 Kung Chong Road Singapore 160143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554600  
 Tel: (+65) 6484 9910 | Fax: (+65) 6481 1903

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 02/12/2022  
Vehicle No: SME8882M  
Model: FERRARI F8 TRIBUTO S-A  
Chassis: ZFF92LMC000262643-2021  
Reg. Year: 2022  
Policy No: DMPPHQ22-005606  
Date of Accident: 07/10/2022

TO MOTOR CLAIM DEPT  
EQ INSURANCE  
5 Maxwell Road, #17-00 Tower Block  
MND Complex  
Singapore 069110

**SUPPLEMENTARY**

| NO.         | DESCRIPTION                                   | QTY | UNIT S\$      | AMOUNT S\$            |
|-------------|-----------------------------------------------|-----|---------------|-----------------------|
| 1           | FRONT DOOR LOCK CABLE LH                      | 1   |               | <i>Ref</i> \$345.00   |
| 2           | COMPL VAPOUR FILTER                           | 1   |               | <i>CM</i> \$3,800.00  |
| 3           | VAPOUR FILTER BRACKET                         | 1   |               | <i>B</i> \$800.00     |
| 4           | CANISTER SHIELD                               | 1   |               | <i>B</i> \$360.00     |
| 5           | REAR SPOILER DUCT LOWER WALL                  | 1   | <i>Ref CM</i> | \$4,500.00            |
| 6           | REAR SPOILER DUCT LOWER WALL "FERRARI" EMBLEM | 1   |               | <i>Ref</i> \$380.00   |
| 7           | ENGINE INTAKE DUCT LH                         | 1   |               | <i>CM</i> \$1,250.00  |
| 8           | INTERCOOLER LH                                | 1   |               | <i>Ref</i> \$7,600.00 |
| 9           | INTERCOOLER BRACKET LH                        | 1   |               | <i>DIY</i> \$225.00   |
| SUB TOTAL   |                                               |     |               | \$19,260.00           |
| LESS 10%    |                                               |     |               | \$1,926.00            |
| PARTS TOTAL |                                               |     |               | \$17,334.00           |

| NO.       | SPECIAL NETT               | QTY | UNIT S\$ | AMOUNT S\$          |
|-----------|----------------------------|-----|----------|---------------------|
| 1         | FERRARI CHASSIS STICKER LH | 1   |          | <i>Ref</i> \$100.00 |
| S/N TOTAL |                            |     |          | \$100.00            |

|         |       |             |
|---------|-------|-------------|
| TING AN | TOTAL | \$17,434.00 |
|---------|-------|-------------|

**Head office**

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112


**Branch**

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-06 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011





Faster  
memory  
speed

• Intel® Celeron

• Intel® UHD Gr

• 4 GB DDR4 Me

**OPTIMA WERKZ**  
SINGAPORE

OPTIMA WERKZ PTE LTD  
Co. Reg. No. 201212455W

www.ow.sg

/OptimaWerkz

/OptimaWerkz

Date : 20/10/2022  
Vehicle No: SME8882M  
Model: FERRARI F8 TRIBUTO S-A  
Chassis: ZFF92LMC000262643-2021  
Reg. Year: 2022  
Policy No: DMPPHQ22-005606  
Date of Accident: 07/10/2022

**TO MOTOR CLAIM DEPT  
EQ INSURANCE**

5 Maxwell Road, #17-00 Tower Block  
MND Complex  
Singapore 069110

TO TUFF KOTE/ANTI-RUST & ETC.

*NZ* \$300.00 *X*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$400.00 *284*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$250.00 *100%*

**LABOUR TOTAL \$10,000.00**

TING AN

**TOTAL**

**\$316,776.50**

**Head office**

0 Kung Chong Road Singapore 190143  
Tel: (+65) 0472 1313 | Fax: (+65) 0472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 0484 9010 | Fax: (+65) 0481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047  
Tel: (+65) 0481 1522 | Fax: (+65) 0481 1011

