

Date : 20/10/2022
 Vehicle No: SME8882M
 Model: FERRARI F8 TRIBUTO S-A
 Chassis: ZFF92LMC000262643-2021
 Reg.Year: 2022
 Policy No: DMPPHQ22-005606
 Date of Accident: 07/10/2022
 Estimator: TING AN

TO MOTOR CLAIM DEPT
 EQ INSURANCE
 5 Maxwell Road, #17-00 Tower Block
 MND Complex
 Singapore 069110

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR LH	1		\$30,000.00
2	FRONT DOOR OUTER HANDLE LH	1		\$1,900.00
3	FRONT DOOR OUTER HANDLE SEAL LH	1		\$180.00
4	FRONT DOOR LOCK LH	1		\$750.00
5	FRONT DOOR LOWER WEATHERSTRIP LH	1		\$1,900.00
6	FRONT DOOR UPPER WEATHERSTRIP LH	1		\$1,650.00
7	FRONT DOOR REGULATOR LH	1		\$2,400.00
8	FRONT DOOR INNER BRACKET LH	1		\$1,000.00
9	REAR FENDER LH	1		\$65,000.00
10	REAR FENDER QUARTER GLASS LH	1		\$2,400.00
11	REAR FENDER INNER SHIELD (FRONT)	1		\$3,800.00
12	REAR FENDER INNER SHIELD (REAR)	1		\$1,600.00
13	SIDE SKIRT CARBON FIBER LH	1		\$36,500.00
14	SIDE SKIRT KICK PLATE LH	1		\$1,200.00
15	SIDE SKIRT RETAINER LH	1		\$140.00
16	REAR AIR INTAKE LH	1		\$2,100.00
17	REAR AIR INTAKE GASKET SHIELD LH	1		\$400.00
18	REAR AIR INTAKE UPPER & LOWER FOAM	1		\$250.00
19	REAR AIR INTAKE SIDE FOAM	1		\$330.00
20	ENGINE COMPARTMENT COVER CARBON FIBER LH	1		\$12,000.00
21	ENGINE COMPARTMENT LID GRILLE LH	1		\$1,800.00
22	ENGINE UNDER COVER	1		\$2,600.00
23	ENGINE UNER COVER BRACKET	1		\$850.00
24	REAR RIM LH	1		\$17,000.00
25	REAR UPPER ARM LH	1		\$2,600.00
26	REAR LOWER ARM LH	1		\$4,200.00
27	REAR KNUCKLE ARM LH	1		\$8,500.00
28	REAR STABILIZER BAR LINK LH	1		\$900.00
29	REAR TIE ROD LH	1		\$1,400.00
30	REAR BUMPER	1		\$39,900.00
31	REAR BUMPER LOWER DIFFUSER CARBON FIBER	1		\$38,400.00
32	REAR SPOILER	1		\$29,000.00
33	REAR SPOILER THIRD BRAKE LIGHT	1		\$900.00

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 20/10/2022
 Vehicle No: SME8882M
 Model: FERRARI F8 TRIBUTO S-A
 Chassis: ZFF92LMC000262643-2021
 Reg.Year: 2022
 Policy No: DMPPHQ22-005606
 Date of Accident: 07/10/2022

TO MOTOR CLAIM DEPT

EQ INSURANCE

5 Maxwell Road, #17-00 Tower Block
 MND Complex
 Singapore 069110

34	REAR SPOILER BRACKET	1		\$1,680.00
35	REAR BUMPER REINFORCEMENT	1		\$5,700.00
36	REAR BUMPER UPPER BRACKET LH	1		\$160.00
37	REAR BUMPER WIRING HARNESS	1		\$4,200.00
38	REAR BUMPER PARKING SENSOR WIRING	1		\$900.00
39	REAR BUMPER REFLECTOR LH	1		\$250.00
40	REAR BUMPER REFLECTOR BASE BRACKET LH	1		\$200.00
41	REAR BUMPER PARKING SENSOR	1		\$350.00
42	REAR BUMPER PARKING SENSOR O-RING	1		\$50.00
43	REAR BUMPER 'FERRARI' EMBLEM	1		\$750.00
44	REAR EXHAUST TIP LH	1		\$220.00
45	REAR EXHAUST MUFFLER LH	1		\$4,500.00
46	REAR EXHAUST BRACKET LH	1		\$185.00
47	REAR EXHAUST MOUNTING	2	\$165.00	\$330.00
48	REAR TAIL LAMP LH (OUTER)	1		\$3,000.00
49	REAR TAIL LAMP LH (INNER)	1		\$3,280.00
50	REAR TAIL LAMP BASE BRACKET LH	1		\$380.00
51	REAR FENDER RH	1		REPAIR
SUB TOTAL				\$339,685.00
LESS 10%				\$33,968.50
PARTS TOTAL				\$305,716.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR INNER TRIM BOARD CLIPS LH	1		\$150.00
2	SIDE SKIRT SCREW & CLIPS	1		\$150.00
3	REAR FENDER QUARTER GLASS SEALANT	1		\$120.00
4	REAR FENDER INNER SHIELD CLIPS LH	1		\$120.00
5	ENGINE COMPARTMENT GRILLE CLIPS	1		\$100.00
6	ENGINE UNDER COVER CLIPS	1		\$120.00
7	REAR BUMPER SCREW	1		\$150.00
8	REAR BUMPER LOWR DIFFUSER SCREW	1		\$150.00
S/N TOTAL				\$1,060.00

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 20/10/2022
 Vehicle No: SME8882M
 Model: FERRARI F8 TRIBUTO S-A
 Chassis: ZFF92LMC000262643-2021
 Reg.Year: 2022
 Policy No: DMPPHQ22-005606
 Date of Accident: 07/10/2022

TO MOTOR CLAIM DEPT

EQ INSURANCE

5 Maxwell Road, #17-00 Tower Block
 MND Complex
 Singapore 069110

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST ACCIDENT AREAS & ETC. \$3,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH, ROCKER PANEL LH, REAR FENDER LH, REAR FENDER RH, REAR BUMPER & ETC. \$2,500.00

LABOUR CHARGES TO DISCONNECT, REMOVE & REFIX FRONT DOOR INNER WIRING HARNESS & ETC. TO EFFECT REPLACE OF FRONT DOOR LH. \$300.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR LH. \$300.00

LABOUR CHARGES TO REMOVE & REFIX INNER TRIM & UPHOLDSTERY SET & ETC. TO EFFECT REPLACE OF REAR FENDER LH. \$500.00

LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS LH & ETC. \$200.00

LABOUR CHARGES TO REMOVE & REPLACE REAR PARKING SENSOR & ETC. \$200.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER WIRING HARNESS & ETC. TO EFFECT REPLACE OF REAR BUMPER, BUMPER LOWER DIFFUSER. \$250.00

LABOUR CHARGES TO REMOVE & REPLACE REAR EXHAUST MUFFLER, REAR EXHAUST MOUNTING, REAR EXHAUST BRACKET & ETC. \$350.00

TO MOUNT VEHICLE ONTO CAR-O-LINER TO CALIBRATE SUB CHASSIS FRAME & BODY BACK TO MANUFACTURING SPECIFICATIONS. \$800.00

LABOUR CHARGES TO REMOVE & REPLACE REAR UPPER ARM LH, REAR LOWER ARM LH, REAR KNUCKLE ARM LH, REAR TIE ROD, REAR STABILIZER BAR LINK & ETC. \$500.00

TO WHEEL ALIGNMENT & BALANCING. \$150.00

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date : 20/10/2022
Vehicle No: SME8882M
Model: FERRARI F8 TRIBUTO S-A
Chassis: ZFF92LMC000262643-2021
Reg.Year: 2022
Policy No: DMPPHQ22-005606
Date of Accident: 07/10/2022

**TO MOTOR CLAIM DEPT
EQ INSURANCE**

5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

TO TUFF KOTE/ANTI-RUST & ETC.	\$300.00
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$400.00
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$250.00

LABOUR TOTAL	\$10,000.00
--------------	-------------

TING AN	TOTAL	\$316,776.50
---------	-------	--------------

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9819 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011