

ASS. REC. BY:

REF:

AIG / 22010423/Kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$40K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 24 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKS13524 Yr Regn: 03, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia ⁴⁷ Forte K3 c.c 1591

Colour: M. Red A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAF8 411MI=5409372

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____ R: 215/45ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Roadstone

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 17/10/22

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 22/10/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

8 15m

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Battery flat

11 Sep @ 16K Cash

Date/Time, File Pass to?

Prell. Report Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: Site Insp (\$), Interview (\$), Tech Invs (\$), Weekend (\$)

Survey Fee:

Transportation, S-RS, St, Fuel, Others

Table with columns for various fees and a TOTAL row.

Report Format :

Lump Sum / I.B.I: (\$)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SKS1352 Y
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Not Authorized

WS Ref: TP/AIG

Claim Type: Third Party

11 Day \$, 71000??

Accident Date: 17/10/2022

24 days

TP Veh Reg No: SMS7893P

Estimate No: ES2291081/YISHUN

Date: 19 Oct 2022

Policy No: 507795037-06

Veh Reg No: **SKS1352Y**

Make/Model: KIA KIA FORTE K3 1.6A

Chassis No: KNAFZ411MF5404372

Engine No: G4FGH768274

Reg. Date: 27/03/2015

Estimate Repair Cost to Vehicle No :SKS1352Y

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Net Price				
1 FRONT BUMPER	874.00	1 PC	<i>Bu</i> 874.00	✓
2 FRONT BUMPER SPONGE	116.00	1 PC	<i>Bu</i> 116.00	✓
3 FRONT BUMPER REINFORCEMENT	492.00	1 PC	<i>Bu</i> 492.00	✓
4 FRONT BUMPER RETAINERS	25.00	2 PCS	<i>CM</i> 50.00	✓
5 FRONT BUMPER CLIPS	3.50	6 PCS	<i>Ne</i> 21.00	✓
6 FRONT BUMPER LOWER GRILLE	70.00	1 PC	<i>Di</i> 70.00	✓
7 FRONT BUMPER LH FOG LAMP	241.00	1 PC	<i>mg CM</i> 241.00	✓
8 FRONT BUMPER LH FOG LAMP GARNISH	14.00	1 PC	<i>ni</i> 14.00	✓
9 FRT BUMPER LOGO	43.00	1 PC	<i>Ne</i> 43.00	✓
10 FRT BUMPER LH PDC SENSOR	187.00	1 PC	<i>Shom</i> 187.00	✓
11 FRONT BUMPER PDC SENSOR WIRE HARNESS	130.00	1 SET	<i>Sw</i> 130.00	✗
12 FRT BUMPER PLATE GARNISH	17.00	1 PC	<i>Bu</i> 17.00	✓
13 FRONT GRILLE	338.00	1 PC	<i>Bu</i> 338.00	✓
14 HEADLAMPS	2,035.00	2 PCS	<i>CM</i> 4,070.00	✓
15 HEADLAMP LOWER BEAMS	25.00	2 PCS	<i>ni/Bu</i> 50.00	✓
16 HEADLAMP CLIPS	3.50	2 PCS	<i>Ne</i> 7.00	✓
17 FRT SUPPORT PANEL	930.00	1 PC	<i>Bu</i> 930.00	✓
18 FRONT SUPPORT PANEL AIR GUIDES	19.00	2 PCS	<i>CM</i> 38.00	✓
19 FRONT SUPPORT PANEL TOP COVER	58.00	1 PC	<i>CM</i> 58.00	✓
20 BONNET	1,993.00	1 PC	<i>Bu</i> 1,993.00	✓
21 BONNET LOCK	65.00	1 PC	<i>Di</i> 65.00	✓
22 BONNET INSULATOR	169.00	1 PC	<i>Di</i> 169.00	✓
23 BONNET INSULATOR CLIPS	3.50	10 PCS	<i>Ne</i> 35.00	✓
24 BONNET HINGES	34.00	2 PCS	<i>Di</i> 68.00	✓
25 FRONT LH FENDER	578.00	1 PC	<i>Bu</i> 578.00	✓
26 FRONT LH FENDER DUST COVER	131.00	1 PC	<i>Di</i> 131.00	✓
27 FRONT LH FENDER DUST COVER CLIPS	3.50	6 PCS	<i>Ne</i> 21.00	✓
28 AIR-CON CONDENSER	774.00	1 PC	<i>Bu</i> 774.00	✓
29 RADIATOR	618.00	1 PC	<i>Bu</i> 618.00	✓
30 RADIATOR FAN ASSY	623.00	1 PC	<i>CM</i> 623.00	✓
31 AIR INTAKE TOP INLET	77.00	1 PC	<i>CM</i> 77.00	✓
32 AIR INTAKE HOSE	75.00	1 PC	<i>CM</i> 75.00	✓
33 AIR INTAKE RESONATOR	144.00	1 PC	<i>Di</i> 144.00	✓
34 AIR INTAKE FILTER ASSY	139.00	1 PC	<i>CM</i> 139.00	✓
35 THROTTLE VALVE	310.00	1 PC	<i>Sw</i> 310.00	✗
36 INLET MANIFOLD	906.00	1 PC	<i>Sw</i> 906.00	✗
37 FUSE BOX ASSY	2,133.00	1 PC	<i>Sw</i> 2,133.00	✗
38 REAR BUMPER	684.00	1 PC	<i>Bu</i> 684.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 17/10/2022
 TP Veh Reg No: SMS7893P

Estimate No: ES2291081/YISHUN
Date: 19 Oct 2022
Policy No: 507795037-06
Veh Reg No: SKS1352Y
Make/Model: KIA KIA FORTE K3 1.6A
Chassis No: KNAFZ411MF5404372
Engine No: G4FGH768274
Reg. Date: 27/03/2015

Estimate Repair Cost to Vehicle No :SKS1352Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
39 REAR BUMPER RETAINERS	29.00	2 PC	CMA 58.00	✓
40 REAR BUMPER CLIPS	3.50	6 PCS	Ma 21.00	✓
41 REAR BUMPER LOWER SKIRT	383.00	1 PC	Ba 383.00	✓
42 REAR BUMPER PDC SENSORS	187.00	3 PCS	Sham 561.00	✓
43 REAR BUMPER PDC SENSOR WIRE HARNESS	173.00	1 SET	Ta 173.00	✓
44 REAR BUMPER REINFORCEMENT	438.00	1 PC	Ba 438.00	✓
45 REAR BUMPER REINFORCEMENT UPPER BRACKETS	6.00	2 PCS	Ba 12.00	✓
46 REAR BUMPER REINFORCEMENT LOWER BRACKETS	6.00	3 PCS	Ma 18.00	✓
47 BOOTLID	1,883.00	1 PC	Ba 1,883.00	✓
48 BOOTLID CENTRE LOGO	44.00	1 PC	Ma 44.00	✓
49 REAR BOOTLID EMBLEM (FORTE K3)	88.00	1 PC	Ma 88.00	✓
50 BOOTLID LH REFLECTOR	710.00	1 PC	CMA 710.00	✓
51 BOOTLID RH REFLECTOR	710.00	1 PC	CMA 710.00	✓
52 BOOTLID WEATHER STRIP	100.00	1 PC	Ca 100.00	✓
53 BOOTLID UPPER LOCK	112.00	1 PC	De 112.00	✓
54 BOOTLID LOCK STICKER	18.00	1 PC	Ma 18.00	✓
55 BOOTLID HINGES	68.00	2 PCS	Ba 136.00	✓
56 BOOTLID INSULATOR	82.00	1 PC	Debona 82.00	✓
57 BOOTLID INSULATOR CLIPS	3.50	8 PCS	Ma 28.00	✓
58 REAR END PANEL	446.00	1 PC	Ba 446.00	✓
59 REAR END PANEL INNER TRIM	58.00	1 PC	De 58.00	✓
60 LH TAILLAMP	843.00	1 PC	Ba 843.00	✓
61 RH TAILLAMP	843.00	1 PC	Ca 843.00	✓
62 LH TAILLAMP PANEL	120.00	1 PC	Ba 120.00	✓
63 REAR LH FENDER	1,900.00	1 PC	Bu 1,900.00	✓
64 REAR LH FENDER DUST COVER	38.00	1 PC	Su 38.00	✗
65 REAR LH FENDER INNER TRIM	156.00	1 PC	Debona 156.00	✓
66 REAR RH FENDER INNER TRIM	156.00	1 PC	u 156.00	✓
67 INNER TRIM CLIPS	3.50	10 PCS	Ma 35.00	✓
68 REAR FLOOR PANEL	602.00	1 PC	Ba/Bu 602.00	✓
69 SPARE TYRE COVER BOARD	159.00	1 PC	De 159.00	✓
70 REAR EXHAUST HEAT SHIELD	60.00	1 PC	Su 60.00	✗
			28,280.00	
		Less 10%	2,828.00	25,452.00
Special Net				
71 FRONT NUMBER PLATE	35.00	1 PC	Ba 35.00	✓
72 RADIATOR COOLANT	30.00	1 UNIT	Ma 30.00	✓
73 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	Ma 40.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 17/10/2022
 TP Veh Reg No: SMS7893P

Estimate No: ES2291081/YISHUN
 Date: 19 Oct 2022
 Policy No: 507795037-06
 Veh Reg No: **SKS1352Y**
 Make/Model: KIA KIA FORTE K3 1.6A
 Chassis No: KNAFZ411MF5404372
 Engine No: G4FGH768274
 Reg. Date: 27/03/2015

Estimate Repair Cost to Vehicle No :SKS1352Y

Description	U/Price	Quantity	List Price	Amount
74 REAR NUMBER PLATE	35.00	1 PC	B 35.00	✓ 140.00
				140.00
Labour				
75 TOWING	50.00	1 LA	50.00	✓
76 PANEL BEATING ON FRT PORTION	1,100.00	1 LA	1,100.00	8000
77 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
78 PUTTY & RESPRAY PAINT FRT BUMPER,BONNET,HINGES,FRT FENDERS,FRT LH DOOR,PILLAR	1,100.00	1 LA	1,100.00	10000
79 PANEL BEATING ON REAR PORTION	2,000.00	1 LA	2,000.00	18000
80 REMOVE & REFIX REAR SEATS,CARPET,TRIMMINGS	120.00	1 LA	120.00	✓
81 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
82 PUTTY & RSPRAY PAINT REAR BUMPER,REAR FENDERS,BOOTLID,HINGES,REAR END PANEL,FLOOR PANEL,WHEEL HOUSE,CHASSIS MEMBERS	1,550.00	1 LA	1,550.00	14000
83 REMOVE & REFIX FUSES BOX ASSY,REPAIR WIER HARNESS AND CHECK WIRING	150.00	1 LA	na 150.00	X
84 REMOVE & REFIX INLET MANIFOLD,THROTTLE VALVE,ETC AND CHECK ENGINE	150.00	1 LA	na 150.00	X
85 RUSTPROOFING	100.00	1 LA	100.00	✓
				6,520.00
				6,520.00

Total S\$ 32,112.00
 Add GST @ 7% 2,247.84
 Total Amount Payable S\$ 34,359.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

 AUTHORIZED SIGNATURE