



Mercedes-Benz

Steve (LKK)

20/10/22, 11.00L

00-11  
EXCH - ?  
PIP

10 12 13

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SMP3922G

Vehicle & Document Information

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
6222366

WIP No 60321  
Reg No/Reg Date SMP3922G / 25/09/2019  
Date In/Mileage / 0  
Chassis No WDD2050402R4757302  
Engine No 27491031651203  
Make/Model MB/MB C 180 AVANTGARDE/AVANTGARDE  
Colour/Trim 021 197 Obsidian B1/ 041 101 ARTICO Leat

SMP3922G

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	17/10/2022/ 15:04	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : DMPCNA00064952202 // 29/09/2022 DRIVE IN/EXCESS : 17/10/2022 // TBA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	960 x 4	2880		<del>3840</del> 4800.00 ✓
A BPIRES RESPRAY BOOT LID, RIGHT REAR FENDER, LEFT REAR FENDER, REAR BUMPER AND REAR END, PANEL.				4000 4800.00 ✓
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT		0.10		380.00 ✓
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE. NETT				120.00 ✓
A BPILAB PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE ALIGNMENT. NETT (photo)		0.07		? X 1000.00 ✓
A BPILAB REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS (photo)				? X 2400.00
A BPILAB INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT. NETT ✓				? X 540.00
A BPILAB REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS, TRIMS BOARDS AND SEATS CUSHIONS FOR NEC. REPAIRS (photo)				960 1200.00 ✓
A BPILAB APPLY CAVITY WAX ON AFFECTED AREAS.				180.00 ✓
A BPILAB				X 120.00 ✓

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR 8500111-X

### ESTIMATE FOR SMP3922G

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No: 60321  
Reg No/Reg Date: SMP3922G / 25/09/2019  
Date In/Mileage: / 0  
Chassis No: WDD2050402R4757302  
Engine No: 27491031651203  
Make/Model: MB/MB C 180 AVANTGARDE/AVANTGARDE  
Colour/Trim: 021 197 Obsidian B1/ 041 101 ARTICO Leat

# SMP3922G

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	17/10/2022/ 15:04	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
TO APPLY SEAL SEAM ON PANEL JOINTS				
M BOOT LID	1.00	2522.70	00.00	2522.70 2777 ✓
M BOOT LID RETAINER WEDGE	2.00	16.34	14.10	28.20 32.68 ✓
M BOOT LID RETAINER WEDGE	2.00	13.19	11.78	23.56 26.38 ✓
M HOLE PLUG	1.00	4.46	00.00	4.46 4.52 ✓
M HOLE PLUG	1.00	4.46	00.00	4.46 4.52 ✓
M HOLE PLUG	2.00	4.52	4.46	8.92 9.04 ✓
M BOOT LID W/STRIP	1.00	210.57	00.00	210.57 213.52 ✓
M BOOT LID CHROME TRIM STRIP	1.00	159.27	00.00	159.27 183.46 ✓
M BOOT LID LOCK	1.00	303.24	00.00	303.24
M BOOT LID SERVO LOCK STRIKER	1.00	490.66	00.00	490.66
M BOOT LID LOCK GEAR MOTOR	1.00	485.66	00.00	485.66
M BOOT LID C180 MODEL PLATE	1.00	120.50	00.00	120.50 132.57 ✓
M BOOT LID MERCEDES STAR	1.00	50.95	00.00	50.95 52.05 ✓
M SEALING GROMMET	3.00	2.39	2.36	7.08 7.17 ✓
M RIGHT REAR LAMP COMBINATION	1.00	746.10	00.00	746.10 785.92 ✓
M RIGHT REAR GASKET FOR LIGHT HOUSING	1.00	22.30	00.00	22.30
M REAR BUMPER	1.00	1890.59	00.00	1890.59 1947.67 ✓
M REAR BUMPER LOWER	1.00	320.61	00.00	320.61 370.69 ✓
M REAR BUMPER LOWER CHROME TRIM STRIP	1.00	308.49	00.00	308.49 310.34 ✓
M RIGHT REAR BASIC MOUNTING FOR BUMPER	1.00	39.83	00.00	39.83 45.86 ✓
M RIGHT REAR BASIC MOUNTING FOR BUMPER	1.00	70.21	00.00	70.21
M REAR BASIC MOUNTING FOR BUMPER	1.00	113.94	00.00	113.94
M REAR CROSS MEMBER	1.00	772.94	00.00	772.94
M RIGHT REAR FENDER COVERING	1.00	49.23	00.00	49.23 50.89 ✓
M REAR END PANEL TRIM GARNISH	1.00	168.28	00.00	168.28
M REAR END PANEL	1.00	1655.71	00.00	1655.71
M TS TWO-COMPONENT ADHESIVE	1.00	858.76	00.00	858.76
M UNDERBODY PROTECTION WAX	1.00	116.04	00.00	116.04 116.39 ✓
M SEAM SEAL	1.00	116.07	00.00	116.07 116.42 ✓

# ESTIMATE

Confirmed & accepted by

**Yik Chan Hoe**

Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@eyalecarriage.com.sg

Nett **27,209.33**  
7% GST on **27209.33** **1904.65**

**Total Payable 29,113.98**

LKK Auto Consultants  
Authorized signatory and company stamp  
Signature: \_\_\_\_\_  
and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.  
Supplementary item(s) must be paid for and is subject to final approval from us.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg