

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 27 Oct 2022

Preliminary Advice

Vehicle No	: SKX6480B	Accident Date	: 15/10/2022
Make	: TOYOTA COROLLA	Policy No.	: DMPCSNW00248912105
Assignment Date	: 20/10/2022	Excess	: S\$0.00
Date of Inspection	: 27/10/2022	Est. Duration of Repair	: 7
Inspection At	: S & H MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,838.81
Revised Amount	:S\$	3,931.81
Check Items (Estimated)	:S\$	1,660.00
Total	:S\$	5,591.81

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	53,000.00
COE / PARF Rebate	:S\$	29,512.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,488.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .