



The Motor Claims Department
M/s China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

File No : SH/2022/272/10/027/OD
Date : 31-October-2022

Supplementary estimated cost of repair for vehicle no: SKX 6480 B Toyota
Policy No: DMPCSHNW00248912105 Accident Date: 15.10.2022

Description	Quantity	Cost Price
1 pc Front left headlamp		\$ <i>my cm</i> 350.00 ✓
1 pc Gearbox oil pan		\$ <i>nd</i> 120.00 ✓
1 pc Gearbox oil pan gasket		\$ <i>me</i> 30.00 ✓
1 pc Front cross member		\$ <i>By</i> 680.00 ✓
Gear Oil		\$ 90.00 <i>500ml</i>
Labour charge for knocking and welding front right & left chassis		\$ 168.00 X