

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/10/2022

User ID : GohKK2

Section A - Accident Details

Registration Number	SG1696Z
Case Reference Number	BUS/10/22/7012
Registration Date	11/2/2016
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	CITARD 0530
Name of Driver	Wang Ke
Type of Accident	Side Swipe
Accident Date and Time	12/10/2022 2:14 PM
Accident Reported Date and Time	14/10/2022 5:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1696Z - left front portion SLG6392A (TP) - INSURED WITH AIG
Prepared Date and Time	15/10/2022 9:08 AM
Chassis Number	WE862808323129413
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$8,512.53	\$0.00
Total Other Cost	\$200.00	\$0.00
TOTAL COST	\$11,710.53	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3 days
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	15/10/2022 9:23 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

• Repair work is subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No legal proceedings are allowed
• Disputes must be referred to the
• Arbitration Board for resolution

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/10/2022

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$2,120.00	1590 ✓
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$878.00	708 ✓
Total Spray Painting & Panel Beating	\$878.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$200.00	? receipt Xnn
Total Other Costs	\$200.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
4006315			ACTIVATOR	1.00	\$80.00	0.00	\$80.00 ✓	Replace	re ✓
4006314			SEALANT SIKAFLEX	10.00	\$37.00	0.00	\$370.00 ✓		re ✓
4006313	CONSUMABLE	SIKAB Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00 ✓	Replace	re ✓
600917			IJ BRACKET	1.00	\$35.00	0.00	\$35.00 ✓	Replace	re ✓
6009901	Body	6283850401	BUMPER-FRONT,CENTRE FOR MB CITARO O530	1.00	\$1,663.80	10.00	\$1,497.42 ✓	Replace	de ✓
6009904	Body	6288850526	FLAP-FRONT,CENTRE FOR MB CITARO O530	1.00	\$1,513.05	10.00	\$1,361.75	Replace	repair ✓
6010399			COVERING ,W/SCREEN EDGE,BOTTOM (CITARO)	1.00	\$545.10	0.00	\$545.10	Replace	repair ✓
6009902	BODY LH	6288800172	BUMPER-FRONT,LH FOR MB CITARO O530	1.00	\$1,767.78	10.00	\$1,591.00	Replace	cm ✓
6009700	VE		LAMP,BLINKER,FRONT, LEFT FOR MB OC 500 LE	1.00	\$155.30	10.00	\$139.77 ✓	Replace	bro ✓
6009509	VE		HEADLAMP FOR MERCEDES OC500 LE, LEFT	1.00	\$1,276.50	10.00	\$1,148.85	Replace	3 Xnn
6010191	VM	9417500184	FASTENER-FRT BUMPER FOR MB CITARO BUS	1.00	\$19.35	10.00	\$17.42 ✓	Replace	re ✓
6010190	VM	9437500084	FASTENER-FRT BUMPER FOR MB CITARO BUS	1.00	\$64.20	10.00	\$57.78 ✓	Replace	re ✓
6010183	VM	6288802314	BRACKET,LH,FRT BUMPER FOR MB CITARO BUS	1.00	\$75.00	10.00	\$67.50	Replace	3 Xnn
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00 ✓	Replace	re ✓
			FRONT NUMBER PLATE	1.00	\$75.00	0.00	\$75.00 ✓	Replace	bt ✓
Total					\$7,462.08		\$7,141.59		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2298
708
? receipt Xnn
4018.39
Suppl - 4264.07
4018.39
4264.07
8282.46
202
6625.96
+ 2298.00
8923.96
HS - \$8,900 / 3 days



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 01/11/2022

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$2,120.00				\$1,590.00		
Total Labour			\$2,120.00				\$1,590.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$878.00				\$708.00		
Total Spray Painting & Panel Beating			\$878.00				\$708.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		6287200478	DOOR PROFILE	1.00	\$850.00	10.00	\$765.00	Replace	Replace
6009895	GLASS	6286712210	WINDSCREEN:FRONT,F OR MB CITARO O530	1.00	\$3,887.85	10.00	\$3,499.07	Replace	Replace
4006315			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
4006314			SEALANT SIKAFLEX	10.00	\$37.00	0.00	\$370.00	Replace	Replace
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
6000917			IU BRACKET	1.00	\$35.00	0.00	\$35.00	Replace	Replace
6009901	Body	6283850401	BUMPER:FRONT,CENTRE, FOR MB CITARO O530	1.00	\$1,663.80	10.00	\$1,497.42	Replace	Replace
6009904	Body	6288850526	FLAP:FRONT,CENTRE,F OR MB CITARO O530	1.00	\$1,513.05	100.00	\$0.00	Replace	Repair
6010399			COVERING ;W/SCREEN EDGE,BOTTOM (CITARO)	1.00	\$545.10	100.00	\$0.00	Replace	Repair
6009902	BODY LH	6288800172	BUMPER:FRONT,LH,FOR MB CITARO O530	1.00	\$1,767.78	10.00	\$1,591.00	Replace	Replace
6009700	VE		LAMP,BLINKER:FRONT, LEFT, FOR MB OC 500 LE	1.00	\$155.30	10.00	\$139.77	Replace	Replace
6009509	VE		HEADLAMP FOR MERCEDES OC500 LE, LEFT	0.00	\$1,276.50	0.00	\$0.00	Replace	Not Given
6010191	VM	9417500184	FASTENER:FRT BUMPER, FOR MB CITARO BUS	1.00	\$19.35	10.00	\$17.42	Replace	Replace
6010190	VM	9437500084	FASTENER:FRT BUMPER, FOR MB CITARO BUS	1.00	\$64.20	10.00	\$57.78	Replace	Replace
6010183	VM	6288802314	BRACKET:LH,FRT BUMPER, FOR MB CITARO BUS	0.00	\$75.00	0.00	\$0.00	Replace	Not Given
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace
			FRONT NUMBER PLATE	1.00	\$75.00	0.00	\$75.00	Replace	Replace
Total					\$12,199.93		\$8,282.46		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

supply cut
supply cra