

A.S.S. REC BY: Taufik

REF: CS/TM/22010438/Tg/y3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<u>me</u>	

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 7587S Yr Regn: 2019 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 336055 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ITDKB3F4103081300

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 175

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 20/10/22

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear A/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh finalised LS \$3200, 3 days. (Red \$2426.78, 43%)

Date/Time, File Pass to?

1) 05/01 Typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Insp (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

Rep. Format: MER-TP

Lump Sum / T.B.R. / 3200

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:**  
**CCPL**

**Tokio Marine Insurance Singapore Ltd (HQ)**

Singapore

*Jumani  
(Loyang)*

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	19/10/2022
Vehicle Reg. No.:	<b>SHC7587S</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 (A)	Vehicle Reg. Date:	30/05/2019
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	2ZR2C27697	Chassis No:	JTDKB3FU103081300
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

**COST OF CLAIMS**

	<b>Amount</b>
Parts	3,935.78
Miscellaneous Items	11.00
Labour	1,680.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>5,626.78</b>
<b>+ GST 7.00% (S\$)</b>	<b>393.87</b>
<b>Nett Amount (S\$)</b>	<b>6,020.65</b>

**This claim is handled by: JUMANI BIN MASUDIN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 20 Oct 2022)**Parts:** 144 TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC7587S/20/10/2022 10:18**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	25.00	0.00	de ✓ *503.04 FL
2	10		*REAR BUMPER CLIPS	25.00	0.00	de ✓ *22.00 FL
3	1		*REAR BUMPER BEAM	25.00	0.00	? *378.32 FL
4	1		*REAR BUMPER UNDER COVER	25.00	0.00	? *654.96 FL
5	1		*REAR BUMPER SIDE BRACKET LH	25.00	0.00	de ✓ *112.70 FL
6	1		*REAR BUMPER TOW COVER	25.00	0.00	x ✓ *82.70 FL
7	1		*BOOTLID OUTSIDE COVER	25.00	0.00	wa ✓ *1,054.71 FL
8	1		*BOOTLID EMBLEM - PRIUS	25.00	0.00	wa ✓ *62.14 FL
9	1		*BOOTLID EMBLEM - HYBRID	25.00	0.00	wa ✓ *62.14 FL
10	1		*BOOTLID EMBLEM - STAR	25.00	0.00	wa ✓ *81.43 FL
11	1		*TAILLAMP ASSY UPPER LH	25.00	0.00	wa ✓ *548.40 FL
12	1		*TAILLAMP ASSY LOWER LH	25.00	0.00	wa ✓ *570.00 FL
13	1		*SEAL-REAR BUMPER SIDE LH	25.00	0.00	x ✓ *148.40 FL
14	1		*COVER- FLOOR PANEL	25.00	0.00	x ✓ *220.50 FL
15	1		*REAR BUMPER UNDER SIDE COVER LH	25.00	0.00	? *232.00 FL
16	1		*ADVERTISEMENT LOGO - BUMPER	0.00	0.00	wa ✓ *50.00 F
17	2		*ADVERTISEMENT LOGO - FENDER	0.00	0.00	wa ✓ *200.00 F
18	1		*REVERSE SENSOR	0.00	0.00	wa ✓ *135.70 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,119.14</b>
<b>- List Item Discount on L Items (\$\$)</b>	<b>1,183.36</b>
<b>Total Parts (\$\$)</b>	<b>3,935.78</b>

ComfortDelGro Engineering Pte Ltd/SHC7587S/20/10/2022 10:18. Not valid without Reference section.

Generated using Merimen e-Claims IEAS



## Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$)

11.00

## Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

525

900.00

2 SPRAYPAINT

New

500

600.00

3 CHECK WIRING

New

30

50.00

4 TUFF KOTE

New

30

50.00

5 REMOVE/REFIX REVERSE SENSOR

New

30

80.00

Gross Labour Cost (\$)

1,680.00

ComfortDelGro Engineering Pte Ltd/SHC7587S/20/10/2022 10:18. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

Tanfer 97495749  
wp 20/10/22 @ 5pm  
L/S Body after repair  
+ 2-3 days  
fugitive the auto-wr

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 20.10.2022 09:50

Page : 1

am: ARC Repair TP(CFSO)1

**JOB CARD** Sales Order:

JC NO305533694

OWNER

AS CITYCAB PTE LTD  
7010070  
OWNER NO. 383 SIN MING DRIVE  
RESS Singapore SINGAPORE 575717  
65551188 (R) (O)  
(P)

OUNT CARD NO.

REGN NO.:

SHC7587S

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)20.10.2022 08:40

DATE/TIME IN

YR OF MANU.

30.05.2019

TARGET DATE

CHASSIS CODE

JTDKB3FU103081300

COMPLETION DATE/TIME:


### JOB DESCRIPTION

Accident Date: 19.10.2022  
ATURE: 3P.19.10.22

/NO

LABOR CODE

DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

Exit Pass

No.: SHC7587S

JU TOKIO

Vehicle No.:

SHC7587S

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard