



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22010439/Uny3q2	
			Date: 09/11/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMD 6393B	Veh. Inspected	GBF 1611A
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2203715/MYE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	20/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KDY2318024362	Colour	SILVER
	Odometer	288332 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	BRIDGESTONE	5 mm
	L/H Front Tyre	195 R15	BRIDGESTONE	5 mm
	R/H Rear Tyre	155 R13 (D)	WEST LAKE	5/5 mm
	L/H Rear Tyre	155 R13 (D)	WEST LAKE	5/5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/10/2022	Inspection Date	25/10/2022
	Survey held at	SHIN AUTOMOBILE & TRADING PTE LTD 15 KAKI BUKIT ROAD 4 #01-46 BARTLEY BIZ CENTRE SINGAPORE 417808		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	