

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010440/AVY3Q2**Date:** 21/02/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00077812201

Claimant Vehicle No : SJS3058X **Insured Vehicle No :** XD5689A

Date of Loss: 17/10/2022 Nature of Claim: TP Claim No: SNM22D207499/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS3058X**

Make & Model: HYUNDAI AVANTE, 1.6 HD (A) Engine No: G4FC9U681766

Reg. Date: 08/08/2009 (Man. Year: 2009) Chassis No: KMH DU41BR9U803515

Colour: Maroon Odometer: 170916 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,453.20	1,287.60	1,165.60	47.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	910.00	540.00	37.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,903.20	2,197.60	1,705.60	43.70
Approved Total (Overridden) (S\$)		1,750.00		
(S\$)	3,903.20	1,750.00	2,153.20	55.16
+ GST 8.00/8.00% (S\$)	312.26	140.00	172.26	55.17
Nett Amount (S\$)	4,215.46	1,890.00	2,325.46	55.17

INSPECTION

Date of Assignment: 20/10/2022

Date Inspected: 25/10/2022 Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	143	HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS3058X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR ASSY RH	Dented	1,616.00 FL	*1,141.00 FL
2	2		*FRT DOOR HINGE RH (TOP/LOWER)	Not Necessary	110.00 FL	*- FL
3	1		*FRT DOOR CENTER CHECK RH	Not Necessary	70.00 FL	*- FL
4	1		*FRT DOOR WEATHERSTRIP RH	Not Necessary	156.00 FL	*- FL
5	1		*FRT SIDE MIRROR ASSY RH	Damaged	439.00 FL	*439.00 FL
6	1		*FRT FENDER RH	Repair	521.00 FL	*- FL
7	1		*FRT VVT EMBLEM RH	Necessary	29.50 FL	*29.50 FL
8	1		*FRT DOOR OUTER HANDLE RH	Not Necessary	125.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					3,066.50	1,609.50
- List Item Discount on L Items 20.00/20.00% (S\$)					613.30	321.90
Total Parts (S\$)					2,453.20	1,287.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	450.00	400.00
2	TO REMOVE,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	150.00	30.00
3	TO REMOVE,REPLACE & TRANSFER DOOR COMPONENTS	New	250.00	80.00
4	TO PUTTY AND SPRAY PAINTING ON FRONT FENDER RH ,FRONT DOOR RH	New	600.00	400.00
Gross Labour Cost (\$\$)			1,450.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >