

Kok Wang Car Grooming
1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605
Hp: 91839633 E-mail: vianong@ymail.com

ESTIMATE REPORT

Vehicle Number : SJH7328Z
 Make And Model : Nissan Latio
 Date of Accident : 17 October 2022

S/No	Parts	QTY	Unit Price	List Price
1	Front door RH ✓ DD	1		\$ 1,074.20 ✓
2	Front door hinge top & bottom RH ✓ BT	2	\$ 58.90	\$ 117.80 ✓
3	Front door weatherstrip RH ✓ TN	1		\$ 93.00 ✓
4	Front door lock RH ✓ Jammed	1		\$ 244.80 ✓
5	Front door outer handle RH ✓ BR	1		\$ 178.60 ✓
6	Front door inner trimboard RH ✓ BR	1		\$ 395.50 ✓
7	Front door window regulator RH ✓ BT	1		\$ 178.30 ✓
8	Front door window regulator motor RH X NN	1		\$ 331.20 X
9	Front door black sticker RH ✓ NEC	1 set		\$ 64.40 ✓
10	Rear door RH ✓ DD	1		\$ 1,074.20 ✓
11	Rear door hinge top & bottom RH ✓ BT	2	\$ 58.90	\$ 117.80 ✓
12	Rear door weatherstrip RH ✓ TN	1		\$ 93.00 ✓
13	Rear door black sticker RH ✓ NEC	1 set		\$ 50.10 ✓
				\$ 4,012.90
				Less 10%
				\$ 401.29
				Total
				\$ 3,611.61

Special Nett Item

1	Front door inner trimboard clips RH ✓ NEC	1 set	\$ 15	60.00
2	Rear door inner trimboard clips RH ✓ NEC	1 set	\$ 15	60.00
3	Panel sealant ✓ NEC	3 tubes	\$ 40	180.00
4	B pillar RH ✓ DD	1	\$	478.00 ✓
5	Rocker panel RH ✓ DD	1	\$	490.00 ✓
6	Side skirt RH ✓ BR	1	\$ 300	350.00
				Total
				\$ 1,618.00


1338

Labour & Misc Charges

To dismantle, replace & panel beating affected portion.	\$	1,200.00	1000
To spray paint on affected portion.	\$	1,200.00	800
To remove/replace/reinstall front door components.	\$	100.00	50
To remove/replace/reinstall rear door components.	\$	100.00	50
To apply anti-rust on affected areas.	\$	200.00	30
To check wiring.	\$	60.00	30

1960

Total **\$ 2,860.00**



Steve (LKK)
 20/10/22
 Without Prejudice
 L/S
 Resurvey After Spray
 7 days

Grand Total : \$ 8,089.61

6611.53

L/S - 5289.22
 = 5300