

Kok Wang Car Grooming
1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605
Hp: 91839633 E-mail: vianong@ymail.com

ESTIMATE REPORT

Vehicle Number : SJH7328Z
 Make And Model : Nissan Latio
 Date of Accident : 17 October 2022


S/No	Parts	QTY	Unit Price	List Price
1	Front door RH ✓ DD	1		\$ 1,074.20
2	Front door hinge top & bottom RH ✓ BT	2	\$ 58.90	\$ 117.80
3	Front door weatherstrip RH ✓ TN	1		\$ 93.00
4	Front door lock RH ✓ Jammed	1		\$ 244.80
5	Front door outer handle RH ✓ BR	1		\$ 178.60
6	Front door inner trimboard RH ✓ BR	1		\$ 395.50
7	Front door window regulator RH ✓ BT	1		\$ 178.30
8	Front door window regulator motor RH X NN	1		\$ 331.20
9	Front door black sticker RH ✓ NEC	1 set		\$ 64.40
10	Rear door RH ✓ DD	1		\$ 1,074.20
11	Rear door hinge top & bottom RH ✓ BT	2	\$ 58.90	\$ 117.80
12	Rear door weatherstrip RH ✓ TN	1		\$ 93.00
13	Rear door black sticker RH ✓ NEC	1 set		\$ 50.10
				\$ 4,012.90
				Less 10%
				\$ 401.29
				Total \$ 3,611.61

Special Nett Item

1	Front door inner trimboard clips RH ✓ NEC	1 set	\$ 15	60.00
2	Rear door inner trimboard clips RH ✓ NEC	1 set	\$ 15	60.00
3	Panel sealant ✓ NEC	3 tubes	\$ 40	180.00
4	B pillar RH ✓ DD	1	\$	478.00
5	Rocker panel RH ✓ DD	1	\$	490.00
6	Side skirt RH ✓ BR	1	\$ 300	350.00
				Total \$ 1,618.00

Labour & Misc Charges

To dismantle, replace & panel beating affected portion.	\$	1,200.00	1000
To spray paint on affected portion.	\$	1,200.00	800
To remove/replace/reinstall front door components.	\$	100.00	50
To remove/replace/reinstall rear door components.	\$	100.00	50
To apply anti-rust on affected areas.	\$	200.00	30
To check wiring.	\$	60.00	30
Total	\$	2,860.00	



Steve (LKK)
20/10/22
Without Prejudice
L/S
Resurvey After Spray
7 days

Grand Total : \$ 8,089.61