



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SMJ 4916A

| Qty | Description of Parts | Condition | Recommended (\$) |
|-----|---|----------------------|------------------|
| | <u>REPLACEMENT OF PARTS</u> | | |
| 1 | COVER FR BUMPER | TO REPAIR SEE LABOUR | - |
| 1 | BRACKET FR BUMPER UPR SIDE MTG | NOT NECESSARY | - |
| 1 | GRILLE FRT BUMPER | GRAZED | 485.00 |
| 1 | ORNAMENT KIA NO. 115 | NECESSARY | 38.00 |
| | LESS 20% DISCOUNT | | -104.60 |
| | | | 418.40 |
| | <u>SPECIAL NETT ITEMS</u> | | |
| 1 | SUNDRIES (SN) | NECESSARY | 20.00 |
| | | | 20.00 |
| | <u>LABOUR</u> | | |
| | RENEW FR BUMPER REPAIR RHF FENDER. INCLUSIVE OF THE REPAIR OF COVER FR BUMPER | | 520.00 |
| | RESPRAY FR BUMPER & RHF FENDER. | | 900.00 |
| | CHECK WIRING ELECTRICAL SYSTEM. | | 50.00 |
| | TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM. | | 160.00 |
| | REMOVE & REFIT FR PARKING ASSIST SENSOR. | | 60.00 |
| | APPLY ANTI CORROSION ON AFFECTED AREAS (NPA). | NOT NECESSARY | - |
| | | | 1,690.00 |
| | GRAND TOTAL | | 2,128.40 |

| | |
|------------------------------------|-----------------|
| RECOMMENDED COST OF REPAIRS | 2,128.40 |
|------------------------------------|-----------------|

Report Ref No. CS1/SPF22010442/Cqy3m4

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.