



AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

T : (65) 6419 3000

www.aig.sg

Claim No: 0288232133SG Date of Survey: 20/07/2022

Repairer: CYCLE & CARRIAGE KIA PTE LTD

REFERENCE

Insured: SIEW PUI YEOK Policy No: 1900017643-02
Date of Loss: 11/06/2022 Nature of Claim: OD

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg. No: SMJ4916A
Make & Model: KIA CERATO, 1.6 SX (A) Reg. Date: 07/03/2019
Engine No: G4FGJH722085 Chassis No: KNAF3416MK5031122

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Kumho 4 mm	Rear Left Side:	Kumho 4 mm
Front Right Side:	Kumho 4 mm	Rear Right Side:	Kumho 4 mm

The above values represent the remaining tyre treads depth

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Footbrake (Serviceable):	Yes	Engine Modification:	No
Handbrake (Serviceable):	Yes	Steering (Serviceable):	Yes
Pre-accident Condition:			

COST OF CLAIMS	Repairer's	Our Offer	Difference	Diff %
Parts	942.40	418.40	524.00	55.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	1,710.00	1,080.00	38.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,732.40	2,128.40	1,604.00	42.98
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	3,132.40	1,528.40	1,604.00	51.21
+ GST 7.00/7.00% (\$\$)	219.27	106.99	112.28	51.21
Nett Amount (\$\$)	3,351.67	1,635.39	1,716.28	51.21

SURVEYOR'S REMARKS

This inspection is conducted on a "Without Prejudice Basis"

Estimated repair period : 3.0 days

Authorised Repair : Yes

Inspection conducted by : Che, Yongseng (AIG Claims Dept)

Signature : _

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FR BUMPER		633.00 FL	Repair
2	1		*BRACKET FR BUMPER UPR SIDE MTG		22.00 FL	Reuse
3	1		*GRILLE FRT BUMPER	GRAZED	485.00 FL	*485.00 FL
4	1		*ORNAMENT KIA NO. 115	NRCESSARY	38.00 FL	*38.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,178.00	523.00
- List Item Discount on L Items 20.00/20.00% (S\$)	235.60	104.60
Total Parts (S\$)	942.40	418.40

AIG Asia Pacific Insurance Pte. Ltd./SMJ4916A/06/09/2022 12:23

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER REPAIR RHF FENDER	New	1,560.00	520.00
2	RESPRAY FR BUMPER & RHF FENDER	New	900.00	900.00
3	CHECK WIRING ELECTRICAL SYSTEM	New	50.00	50.00
4	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	160.00	160.00
5	REMOVE & REFIT FR PARKING ASSIST SENSOR	New	60.00	60.00
6	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	0.00
7	SUNDRIES	New	20.00	20.00
Gross Labour Cost (\$\$)			2,790.00	1,710.00

AIG Asia Pacific Insurance Pte. Ltd./SMJ4916A/06/09/2022 12:23

< END OF REPORT >