



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2304896
3 ANSON ROAD #16-00	INV Date	01/08/2023
SPRINGLEAF TOWER	Reference	CC6/CTI22010443/Kya3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SNF 5793P
Insured Veh.	GBE 911X
Claim No.	SNM22D207516/C02
Policy No.	DMCVSNW00134692100
Accident Date	18/10/2022
Inspection Date	19/10/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI22010443/Kya3q2 Date: 01/08/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 911X	Veh. Inspected	SNF 5793P
Policy No.	DMCVSNW00134692100	Coverage (\$)	0.00
Claim No.	SNM22D207516/C02	Excess (\$)	0.00
Assign From		Assign Date	19/10/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA RAIZE (A)	c.c	1196
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	A202A0006096	Colour	METALLIC DARK BLUE
Odometer	30982 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R16	DUNLOP	8 mm
L/H Front Tyre	195/65 R16	DUNLOP	8 mm
R/H Rear Tyre	195/65 R16	DUNLOP	8 mm
L/H Rear Tyre	195/65 R16	DUNLOP	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/10/2022	Inspection Date	19/10/2022
Survey held at	HWA SENG SPRAY PAINTING PTE LTD 160 SIN MING DRIVE #05-11 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNF 5793P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	O/S HEADLAMP	CUT	3,579.80	3,160.00
1	O/S/F FENDER	BUCKLED	691.70	691.70
1	O/S/F FENDER GARNISH	DISTORTED	105.70	105.70
1	O/S/F FENDER INNER SHIELD	SERVICEABLE	281.50	-
1	FRONT BUMPER	TORN	1,148.50	1,020.00
1	FRONT BUMPER RIGHT RETAINER	DISTORTED	67.90	67.90
1	FRONT BUMPER RIGHT FOG LAMP COVER	MISSING	129.30	129.30
1	FRONT BUMPER GRILLE	CUT	422.60	422.60
1	FRONT BUMPER OUTER MOULDING	SERVICEABLE	237.80	-
1	FRONT BUMPER RIGHT SENSOR	MISSING	340.10	340.10
1	BONNET	TO REPAIR SEE LABOUR	1,294.10	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	855.00	-
1	FRONT BUMPER LOWER SPOILER	DISTORTED	436.30	436.30
	LESS 25% DISCOUNT		-2,397.58	-1,593.40
			7,192.72	4,780.20
LABOUR				
	PANEL KNOCKING. INCLUSIVE OF THE REPAIR OF BONNET AND FRONT BUMPER REINFORCEMENT.		750.00	450.00
	SPRAY PAINTING.		800.00	600.00
	WIRE CHECKING.		80.00	20.00
			1,630.00	1,070.00
GRAND TOTAL			8,822.72	5,850.20
RECOMMENDED COST OF REPAIRS				5,850.20

Report Ref No. CC6/CTI22010443/Kya3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNF 5793P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

