

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010449/UQY3Q2**Date:** 08/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00152592101

Claimant Vehicle No : FW5447U **Insured Vehicle No :** GBF5738S

Date of Loss: 29/09/2022 Nature of Claim: TP Claim No: SNM22D206997/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FW5447U**

Make & Model: HONDA NF125MD, 125cc Engine No: NF125MDE5001610

Reg. Date: 11/04/2003 (Man. Year: 2003) Chassis No: NF125MD5001610

Colour: Blue Odometer: 99999 km

Engine Capacity: 125 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80-80-17 Rear Tyre Size: 80-90-17

Front Left Side: Dunlop 6 mm Rear Left Side: Timsun 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,669.50	1,278.00	391.50	23.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	420.00	300.00	120.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,089.50	1,578.00	511.50	24.48
Approved Total (Overridden) (\$\$)		800.00		
Nett Amount (\$\$)	2,089.50	800.00	1,289.50	61.71

INSPECTION

Date of Assignment: 21/10/2022

Date Inspected: 21/10/2022 Inspected At: F T FASTTRACK
25 KAKI BUKIT ROAD 4
#01-77 SYNERGY @ KB
SINGAPORE 417800

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Nov 2022)	
Parts:	N/A	HONDA NF125MD 125cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FW5447U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER	Broken	135.00 FL	*135.00 FL
2	1		*TAIL LAMP	Broken	105.00 FL	*105.00 FL
3	1		*NO PLATE HOLDER	Missing	48.00 FL	*48.00 FL
4	1		*REAR NO PLATE	Missing	20.00 FL	*10.00 FL
5	1		*NO PLATE LIGHT	Missing	97.00 FL	*97.00 FL
6	2		*SIDE COVER (LH) & (RH)	Cracked	190.00 FL	*190.00 FL
7	1		*TOP BOX	Damaged	250.00 FL	*250.00 FL
8	1		*RACK	Bent	90.00 FL	*90.00 FL
9	1		*BOX BASE	Cracked	50.00 FL	*50.00 FL
10	1		*MIRROR (RH)	Cut	45.00 FL	*45.00 FL
11	1		*BRAKE LEVER	Cut	25.00 FL	*25.00 FL
12	1		*FRONT FENDER	Repair	90.00 FL	*- FL
13	1		*FRONT SIGNAL LAMP (RH)	Cracked	75.00 FL	*75.00 FL
14	1		*FRONT FOOTREST BRACKET	Bent	97.00 FL	*97.00 FL
15	1		*FOOTREST RUBBER	Torn	30.00 FL	*30.00 FL
16	1		*REAR FOOTREST BRACKET	Not Necessary	115.00 FL	*- FL
17	1		*EXHAUST COVER	Bent	118.00 FL	*118.00 FL
18	1		*TAIL COVER	Cracked	35.00 FL	*35.00 FL
19	1		*BRAKE PEDAL	Repair	125.00 FL	*- FL
20	1		*BALANCER (RH)	Cut	20.00 FL	*20.00 FL
21	1		*COVER (RH) OUTER	Repair	95.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,855.00	1,420.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	185.50	142.00
Total Parts (\$\$)	1,669.50	1,278.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT FEE	New	70.00	0.00
2	LABOUR CHARGE	New	350.00	300.00
Gross Labour Cost (S\$)			420.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >